

Relevant Service Information

Gulfstream Aerospace LP has issued Alert Service Bulletin 1125-32A-233, Revision 1, dated August 1, 2003. The service bulletin describes procedures for adjusting the ground contact switches of the MLG. Accomplishing the actions specified in the service information is intended to adequately address the unsafe condition. The CAAI mandated the service information and issued Israeli airworthiness directive 32-03-08-05, dated September 4, 2003, to ensure the continued airworthiness of these airplanes in Israel.

FAA's Determination and Requirements of the Proposed AD

These airplane models are manufactured in Israel and are type certificated for operation in the United States under the provisions of section 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement, the CAAI has kept the FAA informed of the situation described above. We have examined the CAAI's findings, evaluated all pertinent information, and determined that AD action is necessary for products of this type design that are certificated for operation in the United States.

Therefore, we are proposing this AD, which would require adjusting the ground contact switches of the MLG. The proposed AD would require you to use the service information described previously to perform these actions, except as discussed under "Difference Between the Proposed AD and Service Bulletin."

Difference Between the Proposed AD and the Service Bulletin

Operators should note that, although the Accomplishment Instructions of the referenced service bulletin describe procedures for submitting a service reply card, this proposed AD would not require that action. We do not need this information from operators.

Costs of Compliance

This proposed AD would affect about 106 airplanes of U.S. registry. The proposed actions would take about 3 work hours per airplane, at an average labor rate of \$65 per work hour. Based on these figures, the estimated cost of the proposed AD for U.S. operators is \$20,670, or \$195 per airplane.

Regulatory Findings

We have determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not

have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that the proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD. See the **ADDRESSES** section for a location to examine the regulatory evaluation.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

Gulfstream Aerospace LP (Formerly Israel Aircraft Industries, Ltd.): Docket No. FAA-2004-19138; Directorate Identifier 2004-NM-102-AD.

Comments Due Date

(a) The Federal Aviation Administration must receive comments on this AD action by November 3, 2004.

Affected ADs

(b) None.

Applicability

(c) This AD applies to Gulfstream Aerospace LP Model Gulfstream 100 airplanes; and Model Astra SPX and 1125 Westwind Astra series airplanes; serial numbers 004 through 127 inclusive; certificated in any category.

Unsafe Condition

(d) This AD was prompted by two occurrences of uncommanded deployments of the ground airbrakes during descent. We are issuing this AD to prevent a false "Ground" position signal, which could result

in deployment of the ground airbrakes and reduced controllability of the airplane.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Corrective Action

(f) Within 250 flight hours after the effective date of this AD, adjust the ground contact switches of the left and right main landing gear, in accordance with the Accomplishment Instructions of Gulfstream Alert Service Bulletin 1125-32A-233, Revision 1, dated August 1, 2003. Although the service bulletin referenced in this AD specifies to submit certain information to the manufacturer, this AD does not include that requirement.

Alternative Methods of Compliance (AMOCs)

(g) The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

Related Information

(h) Israeli airworthiness directive 32-03-08-05, dated September 4, 2003, also addresses the subject of this AD.

Issued in Renton, Washington, on September 15, 2004.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 04-22193 Filed 10-1-04; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2004-19157; Directorate Identifier 2004-NE-30-AD]

RIN 2120-AA64

Airworthiness Directives; Rolls-Royce Deutschland (RRD) (Formerly Rolls-Royce plc) Tay 650-15 Series Turbofan Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for certain RRD Tay 650-15 series turbofan engines. This proposed AD would require inspection of the high pressure compressor (HPC) shaft and high pressure turbine (HPT) shaft for spline flank wear. This proposed AD results from a number of occurrences of excessive HPC shaft and HPT shaft

spline flank wear discovered during on-wing and in-shop inspections. We are proposing this AD to prevent spline disengagement resulting in an overspeed event, which could lead to an uncontained engine failure and possible damage to the airplane.

DATES: We must receive any comments on this proposed AD by December 3, 2004.

ADDRESSES: Use one of the following addresses to submit comments on this proposed AD.

- DOT Docket Web site: Go to <http://dms.dot.gov> and follow the instructions for sending your comments electronically.
- Government-wide rulemaking Web site: Go to <http://www.regulations.gov> and follow the instructions for sending your comments electronically.
- Mail: Docket Management Facility; U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC 20590-001.
- Fax: (202) 493-2251.
- Hand Delivery: Room PL-401 on the plaza level of the Nassif Building, 400 Seventh Street, SW., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

You can get the service information identified in this proposed AD from Rolls-Royce Deutschland Ltd & Co KG, Eschenweg 11, D-15827 Dahlewitz, Germany; telephone 49 (0) 33-7086-1768; fax 49 (0) 33-7086-3356.

You may examine the comments on this proposed AD in the AD docket on the Internet at <http://dms.dot.gov>.

FOR FURTHER INFORMATION CONTACT: Ian Dargin, Aerospace Engineer, Engine Certification Office, FAA, Engine and Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803-5299; telephone (781) 238-7178; fax (781) 238-7199.

SUPPLEMENTARY INFORMATION:

Docket Management System (DMS)

We have implemented new procedures for maintaining AD dockets electronically. As of May 17, 2004, we post new AD actions on the DMS and assign a DMS docket number. We track each action and assign a corresponding Directorate identifier. The DMS docket No. is in the form "Docket No. FAA-200X-XXXX." Each DMS docket also lists the Directorate identifier ("Old Docket Number") as a cross-reference for searching purposes.

Comments Invited

We invite you to submit any written relevant data, views, or arguments regarding this proposal. Send your

comments to an address listed under **ADDRESSES**. Include "Docket No. FAA-2004-19157; Directorate Identifier 2004-NE-30-AD" in the subject line of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of the proposed AD. We will consider all comments received by the closing date and may amend the proposed AD in light of those comments.

We will post all comments we receive, without change, to <http://dms.dot.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact with FAA personnel concerning this proposed AD. Using the search function of the DMS Web site, anyone can find and read the comments in any of our dockets, including the name of the individual who sent the comment (or signed the comment on behalf of an association, business, labor union, etc.). You may review the DOT's complete Privacy Act Statement in the **Federal Register** published on April 11, 2000 (65 FR 19477-78) or you may visit <http://dms.dot.gov>.

We are reviewing the writing style we currently use in regulatory documents. We are interested in your comments on whether the style of this document is clear, and your suggestions to improve the clarity of our communications that affect you. You can get more information about plain language at <http://www.faa.gov/language> and <http://www.plainlanguage.gov>.

Examining the AD Docket

You may examine the docket that contains the proposal, any comments received, and any final disposition in person at the DMS Docket Offices between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Office (telephone (800) 647-5227) is located on the plaza level of the Department of Transportation Nassif Building at the street address stated in **ADDRESSES**. Comments will be available in the AD docket shortly after the DMS receives them.

Discussion

The Civil Aviation Authority (CAA), which is the airworthiness authority for the United Kingdom, recently notified us that an unsafe condition might exist on certain RRD Tay 650-15 series turbofan engines. The CAA advises that the spline flanks on the HPC shaft and HPT shaft may be developing excessive wear. The amount of wear is directly related to the amount of relative movement between the HPC and an

immobilized HPT. You can detect wear by inspecting the engine to determine the amount of relative movement between the HPC and an immobilized HPT. On-wing and in-shop inspections found excessive spline flank wear on HPC shafts and HPT shafts that incorporated Service Bulletin (SB) No. TAY-72-1327 (hard coated abutment face) and HPC shafts and HPT shafts that did not incorporate SB No. TAY-72-1327.

Relevant Service Information

We have reviewed and approved the technical contents of RRD SB No. TAY-72-1485, Revision 2, dated March 21, 2003 that describes procedures for inspecting the flanks on the HPC shaft and HPT shaft for wear. The CAA classified the initial Rolls-Royce plc (RR) SB as mandatory and issued airworthiness directive CAA 001-01-2002, dated January 11, 2002 in order to ensure the airworthiness of these RR engines in the United Kingdom. Subsequently, the certification responsibility was transferred to RRD and Revision 1 and Revision 2 were reclassified to "Recommended" by the Luftfahrt-Bundesamt (LBA), which is the aviation authority for Germany.

Differences Between This Proposed AD and the Manufacturer's Service Information

The RRD SB No. TAY-72-1485, Revision 2, dated March 21, 2003 specifies compliance times based on the date of receipt of the SB. We have mandated compliance times based on the effective date of this proposed AD.

At initial inspection, if the HPC shaft or HPT shaft has accumulated 3,000 flight cycles or more, RRD SB No. TAY-72-1485, dated January 11, 2002, specifies compliance within 12 months. At initial inspection, if the HPC shaft or HPT shaft has accumulated 3,000 flight cycles or more, we specify compliance within six months from the effective date of the final rule.

FAA's Determination and Requirements of the Proposed AD

This engine model, manufactured in Germany, is type-certificated for operation in the United States under the provisions of section 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. In keeping with this bilateral airworthiness agreement, the CAA and LBA have kept us informed of the situation described above. We have examined the findings of the CAA and LBA, reviewed all available information, and determined that AD action is necessary for products

of this type design that are certificated for operation in the United States. We are proposing this AD, which would require inspecting the spline flanks on the HPC shaft and HPT shaft for wear. The proposed AD would require you to use the service information described previously to perform these actions.

Costs of Compliance

There are about 390 RRD Tay 650–15 series turbofan engines of the affected design in the worldwide fleet. We estimate that 172 engines installed on airplanes of U.S. registry would be affected by this proposed AD. We also estimate that it would take about 4 work hours per engine to perform the proposed actions, and that the average labor rate is \$65 per work hour. Based on these figures, we estimate the total cost of the proposed AD to U.S. operators, per inspection cycle, to be \$44,720. We also estimate, for the HPC shaft of 172 engines to be replaced at teardown, with a parts cost of approximately \$13,862 per shaft, the total cost of the proposed AD to U.S. operators to be \$2,384,264.

Regulatory Findings

We have determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that the proposed regulation:

1. Is not a “significant regulatory action” under Executive Order 12866;
2. Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a summary of the costs to comply with this proposal and placed it in the AD Docket. You may get a copy of this summary at the address listed under **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The Federal Aviation Administration (FAA) amends § 39.13 by adding a new airworthiness directive (AD) to read as follows:

Roll-Royce Deutschland Ltd & Co KG (RRD) (Formerly Rolls-Royce plc): Docket No. FAA–2004–19157; Directorate Identifier 2004–NE–30–AD.

Comments Due Date

(a) The FAA must receive comments on this AD action by December 3, 2004.

Affected ADs

(b) None.

Applicability

(c) This AD applies to RRD Tay 650–15 series turbofan engines. These engines are installed on, but not limited to, Fokker F100 airplanes.

Unsafe Condition

(d) This AD results from a number of occurrences of excessive high pressure compressor (HPC) and high pressure turbine (HPT) shaft spline wear and spline flank wear discovered during on-wing and in-shop inspections. We are issuing this AD to prevent spline disengagement resulting in an overspeed event, which could lead to an uncontained engine failure and possible damage to the airplane.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified unless the actions have already been done.

Initial Visual Inspection of the HPC Shaft and HPT Shaft Splines

(f) Within the compliance times specified in Table 1 of this AD, perform initial inspections of the HPC shaft splines and HPT shaft splines of RRD Tay 650–15 series turbofan engines. Use paragraph 3.A. of Accomplishment Instructions of RRD Service Bulletin (SB) No. TAY–72–1485, Revision 2, dated March 21, 2003, to do the inspections. Calculate spline wear using Appendix 1, paragraph 4.K., of RRD SB No. TAY–72–1485, Revision 2, dated March 21, 2003.

TABLE 1.—HPC SHAFT SPLINES AND HPT SHAFT SPLINES INSPECTION SCHEDULE

Current shaft life	Action
(1) If the HPC shaft or HPT shaft has accumulated 3,000 cycles-since-new (CSN) or more on the effective date of this AD.	Inspect HPC shaft splines and HPT shaft splines for wear within six months after the effective date of this AD, unless previously done. Wait until the HPC shaft or HPT shaft has accumulated 3,000 flight cycles, then inspect the HPC shaft splines and HPT shaft splines for wear within 300 cycles-since-last visual inspection (CSLI) or remainder of 12 months from the effective date of this AD, whichever is greater.
(2) If the HPC shaft or HPT shaft has accumulated fewer than 3,000 CSN on the effective date of this AD.	

(g) Disposition the HPC shaft, HPT shaft, or engine as specified in Table 2 of this AD.

TABLE 2.—VISUAL INSPECTION CRITERIA

Inspection limits	Disposition
(1) If spline wear is 0.1 inch or greater	Remove engine from service within 50 cycles-since-last visual inspection (CSLI).
(2) If spline wear is greater than or equal to 0.06 inch but less than 0.1 inch.	Remove engine from service within 500 CSLI.
(3) If spline wear is greater than or equal to 0.03 inch but less than 0.06 inch..	Inspect HPC shaft and HPT shaft using the intervals in paragraph (h)(1) of this AD.

TABLE 2.—VISUAL INSPECTION CRITERIA—Continued

Inspection limits	Disposition
(4) If spline wear is less than 0.03 inch	Inspect HPC shaft and HPT shaft using the intervals in paragraph (h)(2) of this AD.

Repetitive Visual Inspection of the HPC Shaft and HPT Shaft Splines

(h) Perform repetitive inspections of the HPC shaft splines and HPT shaft splines of RRD Tay 650–15 series turbofan engines. Use paragraph 3.A. of Accomplishment Instructions with Appendix 1 of RRD SB No. TAY–72–1485, Revision 2, dated March 21, 2003, to do the inspections. Calculate spline wear using Appendix 1, paragraph 4.K., of RRD SB No. TAY–72–1485, Revision 2, dated March 21, 2003.

(1) If wear measured in paragraph (f) of this AD was greater than or equal to 0.03 inch but less than 0.06 inch, repetitively inspect HPC shaft and HPT shaft within 1,000 cycles-since-last visual inspection (CSLI).

(2) If wear measured in paragraph (f) of this AD was less than 0.03 inch, repetitively inspect HPC shaft and HPT shaft within 5,500 CSLI.

(i) Disposition the HPC shaft, HPT shaft, or engine as specified in Table 2 of this AD.

Previous Credit

(j) Previous credit is allowed for performing the initial inspections in paragraph (f) of this AD, that were done using the Accomplishment Instructions of one of the following, before the effective date of this AD:

(1) SB No. TAY–72–1485, dated January 11, 2002;

(2) SB No. TAY–72–1485, Revision 1, dated January 29, 2003; and

(3) SB No. TAY–72–1485, Revision 2, dated March 21, 2003.

Material Incorporated by Reference

(k) None.

Related Information

(l) Civil Aviation Authority (CAA) airworthiness directive 001–01–2002, dated January 11, 2002, also addresses the subject of this AD.

Issued in Burlington, Massachusetts, on September 24, 2004.

Francis A. Favara,

Acting Manager, Engine and Propeller Directorate, Aircraft Certification Service. [FR Doc. 04–22192 Filed 10–1–04; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2004–19228; Directorate Identifier 2004–NM–77–AD]

RIN 2120–AA64

Airworthiness Directives; Boeing Model 707 Airplanes and Model 720 and 720B Series Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for all Boeing Model 707 airplanes and Model 720 and 720B series airplanes. This proposed AD would require repetitive inspections of the left and right support ribs for the main landing gear (MLG) trunnion, related investigative/corrective actions if necessary, and other specified actions. This proposed AD is prompted by reports of in-service cracking of the support ribs for the MLG trunnion. We are proposing this AD to detect and correct corrosion and cracking of the support ribs for the MLG trunnion, which could result in collapse of the MLG.

DATES: We must receive comments on this proposed AD by November 18, 2004.

ADDRESSES: Use one of the following addresses to submit comments on this proposed AD.

- DOT Docket Web site: Go to <http://dms.dot.gov> and follow the instructions for sending your comments electronically.

- Government-wide rulemaking Web site: Go to <http://www.regulations.gov> and follow the instructions for sending your comments electronically.

- Mail: Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street SW., Nassif Building, Room PL–401, Washington, DC 20590.

- By fax: (202) 493–2251.

- Hand Delivery: Room PL–401 on the plaza level of the Nassif Building, 400 Seventh Street SW., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Boeing

Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124–2207.

You can examine the contents of this AD docket on the Internet at <http://dms.dot.gov>, or at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street SW., Room PL–401, on the plaza level of the Nassif Building, Washington, DC.

FOR FURTHER INFORMATION CONTACT:

Technical information: Candice Gerretsen, Aerospace Engineer, Airframe Branch, ANM–120S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98055–4056; telephone (425) 917–6428; fax (425) 917–6590.

Plain language information: Marcia Walters, marcia.walters@faa.gov.

SUPPLEMENTARY INFORMATION:

Docket Management System (DMS)

The FAA has implemented new procedures for maintaining AD dockets electronically. As of May 17, 2004, new AD actions are posted on DMS and assigned a docket number. We track each action and assign a corresponding directorate identifier. The DMS AD docket number is in the form “Docket No. FAA–2004–99999.” The Transport Airplane Directorate identifier is in the form “Directorate Identifier 2004–NM–999–AD.” Each DMS AD docket also lists the directorate identifier (“Old Docket Number”) as a cross-reference for searching purposes.

Comments Invited

We invite you to submit any written relevant data, views, or arguments regarding this proposed AD. Send your comments to an address listed under **ADDRESSES**. Include “Docket No. FAA–2004–19228; Directorate Identifier 2004–NM–77–AD” in the subject line of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of the proposed AD. We will consider all comments submitted by the closing date and may amend the proposed AD in light of those comments.

We will post all comments we receive, without change, to <http://dms.dot.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact with FAA personnel concerning this proposed AD.