

0420-2420
0421-2421
0422-2422
0423-2423
0430-2430
0432-2432
0433-2433
0434-2434
0440-2440
0441-2441
0442-2442
0515-2515
0519-2519
0710-2710
0711-2711
0712-2712
0719-2719
0720-2720
0724-2724
0730-2730
0739-2739
0740-2740
0749-2749
0750-2750
0759-2759
0813-2813
0830-2830
0839-2839
0863-2863
0910-2910
0911-2911
0912-2912
0913-2913
0914-2914
0915-2915
0918-2918
0919-2919
0920-2920
0921-2921
0929-2929
0960-2960
1010-3010
1011-3011
1012-3012
1019-3019
1020-3020
1021-3021
1022-3022
1023-3023
1030-3030
1031-3031
1039-3039
1040-3040
1041-3041
1049-3049
1070-3070
1110-3110
1111-3111
1113-3113
1119-3119
1120-3120
1122-3122
1123-3123
1130-3130
1131-3131
1140-3140
1149-3149
1163-3163

Federal Reserve District to read as follows:

APPENDIX A TO PART 229—
ROUTING NUMBER GUIDE TO NEXT-DAY AVAILABILITY CHECKS AND LOCAL CHECKS

* * * * *

Fourth Federal Reserve District
[Federal Reserve Bank of Cleveland]

Head Office

0220-2220
0223-2223
0410-2410
0412-2412
0420-2420
0421-2421
0422-2422
0423-2423
0430-2430
0432-2432
0433-2433
0434-2434
0440-2440
0441-2441
0442-2442
0515-2515
0519-2519
0710-2710
0711-2711
0712-2712
0719-2719
0720-2720
0724-2724
0730-2730
0739-2739
0740-2740
0749-2749
0750-2750
0759-2759
0813-2813
0830-2830
0839-2839
0863-2863
0910-2910
0911-2911
0912-2912
0913-2913
0914-2914
0915-2915
0918-2918
0919-2919
0920-2920
0921-2921
0929-2929
0960-2960
1010-3010
1011-3011
1012-3012
1019-3019
1020-3020
1021-3021
1022-3022
1023-3023
1030-3030
1031-3031
1039-3039
1040-3040
1041-3041
1049-3049
1070-3070
1110-3110
1111-3111

1113-3113
1119-3119
1120-3120
1122-3122
1123-3123
1130-3130
1131-3131
1140-3140
1149-3149
1163-3163
1210-3210
1211-3211
1212-3212
1213-3213
1220-3220
1221-3221
1222-3222
1223-3223
1224-3224
1230-3230
1231-3231
1232-3232
1233-3233
1240-3240
1241-3241
1242-3242
1243-3243
1250-3250
1251-3251
1252-3252

* * * * *

By order of the Board of Governors of the Federal Reserve System, acting through the Secretary of the Board under delegated authority, October 8, 2009.

Jennifer J. Johnson,
Secretary of the Board.

[FR Doc. E9-24634 Filed 10-14-09; 8:45 am]
BILLING CODE 6210-01-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2009-0909; Directorate Identifier 2009-NM-172-AD; Amendment 39-16045; AD 2007-23-05 R1]

RIN 2120-AA64

Airworthiness Directives; Saab AB, Saab Aerosystems Model SAAB 2000 Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule; request for comments.

SUMMARY: We are adopting a new airworthiness directive (AD) for the products listed above that would revise an existing AD. This AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

■ 3. Effective November 14, 2009, the Fourth and Twelfth District routing symbol lists in appendix A are amended by removing the headings and listings for the Twelfth Federal Reserve District and revising the listings for the Fourth

Subsequent to accidents involving Fuel Tank System explosions in flight * * * and on ground, * * * Special Federal Aviation Regulation 88 (SFAR88) * * * required a safety review of the aircraft Fuel Tank System * * *.

* * * * *

Fuel Airworthiness Limitations are items arising from a systems safety analysis that have been shown to have failure mode(s) associated with an 'unsafe condition' * * *. These are identified in Failure Conditions for which an unacceptable probability of ignition risk could exist if specific tasks and/or practices are not performed in accordance with the manufacturers' requirements.

This AD requires actions that are intended to address the unsafe condition described in the MCAI.

DATES: This AD becomes effective October 30, 2009.

On December 11, 2007 (72 FR 62564, November 6, 2007), the Director of the Federal Register approved the incorporation by reference of certain publications listed in the AD.

We must receive comments on this AD by November 30, 2009.

ADDRESSES: You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* (202) 493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.
- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-40, 1200 New Jersey Avenue, SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this AD, contact Saab Aircraft AB, SAAB Aerosystems, SE 581 88, Linköping, Sweden; telephone +46 13 18 5591; fax +46 13 18 4874; e-mail saab2000.techsupport@saabgroup.com; Internet <http://www.saabgroup.com>.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Shahram Daneshmandi, Aerospace

Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-1112; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:

Discussion

On October 27, 2007, we issued AD 2007-23-05, Amendment 39-15251 (72 FR 62564, November 6, 2007). That AD applied to all Saab Model SAAB 2000 airplanes. That AD required revising the Airworthiness Limitations Section (ALS) of the Instructions for Continued Airworthiness.

Critical design configuration control limitations (CDCCLs) are limitation requirements to preserve a critical ignition source prevention feature of the fuel tank system design that is necessary to prevent the occurrence of an unsafe condition. The purpose of a CDCCL is to provide instruction to retain the critical ignition source prevention feature during configuration change that may be caused by alterations, repairs, or maintenance actions. A CDCCL is not a periodic inspection.

Since we issued that AD, we have determined that it is necessary to clarify the AD's intended effect on spare and on-airplane fuel tank system components, regarding the use of maintenance manuals and instructions for continued airworthiness.

Section 91.403(c) of the Federal Aviation Regulations (14 CFR 91.403(c)) specifies the following:

No person may operate an aircraft for which a manufacturer's maintenance manual or instructions for continued airworthiness has been issued that contains an airworthiness limitation section unless the mandatory * * * procedures * * * have been complied with.

Some operators have questioned whether existing components affected by the new CDCCLs must be reworked. We did not intend for the AD to retroactively require rework of components that had been maintained using acceptable methods before the effective date of the AD. Owners and operators of the affected airplanes therefore are not required to rework affected components identified as airworthy or installed on the affected airplanes before the required revisions of the ALS. But once the CDCCLs are incorporated into the ALS, future maintenance actions on components must be done in accordance with those CDCCLs.

FAA's Determination

This product has been approved by the aviation authority of another

country, and is approved for operation in the United States.

Differences Between the AD and the MCAI or Service Information

We have reviewed the MCAI and related service information and, in general, agree with their substance. But we might have found it necessary to use different words from those in the MCAI to ensure the AD is clear for U.S. operators and is enforceable. In making these changes, we do not intend to differ substantively from the information provided in the MCAI and related service information.

We might also have required different actions in this AD from those in the MCAI in order to follow FAA policies. Any such differences are highlighted in a note within the AD.

FAA's Justification and Determination of the Effective Date

This revision merely clarifies the intended effect on spare and on-airplane fuel tank system components, and makes no substantive change to the AD's requirements. For this reason, it is found that notice and opportunity for prior public comment for this action are unnecessary, and good cause exists for making this amendment effective in less than 30 days.

Comments Invited

This AD is a final rule that involves requirements affecting flight safety, and we did not precede it by notice and opportunity for public comment. We invite you to send any written relevant data, views, or arguments about this AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2009-0909; Directorate Identifier 2009-NM-172-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this AD. We will consider all comments received by the closing date and may amend this AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this AD.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more

detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this AD:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD and placed it in the AD docket.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

■ Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by removing amendment 39-15251 (72 FR 62564, November 6, 2007) and adding the following new AD:

2007-23-05 R1 Saab AB, Saab

Aerosystems: Amendment 39-16045.

Docket No. FAA-2009-0909; Directorate Identifier 2009-NM-172-AD.

Effective Date

(a) This airworthiness directive (AD) becomes effective October 30, 2009.

Affected ADs

(b) This AD revises AD 2007-23-05.

Applicability

(c) This AD applies to all Saab AB, Saab Aerosystems Model SAAB 2000 airplanes, certificated in any category, all serial numbers.

Note 1: This AD requires revisions to certain operator maintenance documents to include new inspections. Compliance with these inspections is required by 14 CFR 91.403(c). For airplanes that have been previously modified, altered, or repaired in the areas addressed by these inspections, the operator may not be able to accomplish the inspections described in the revisions. In this situation, to comply with 14 CFR 91.403(c), the operator must request approval for an alternative method of compliance according to paragraph (g) of this AD. The request should include a description of changes to the required inspections that will ensure the continued operational safety of the airplane.

Subject

(d) Air Transport Association (ATA) of America Code 28: Fuel.

Reason

(e) The mandatory continuing airworthiness information (MCAI) states: Subsequent to accidents involving Fuel Tank System explosions in flight * * * and on ground, the FAA published Special Federal Aviation Regulation 88 (SFAR 88) in June 2001. SFAR 88 required a safety review of the aircraft Fuel Tank System to determine that the design meets the requirements of FAR (Federal Aviation Regulation) § 25.901 and § 25.981(a) and (b).

A similar regulation has been recommended by the JAA (Joint Aviation Authorities) to the European National Aviation Authorities in JAA letter 04/00/02/07/03-L024 of 3 February 2003. The review was requested to be mandated by NAA's (National Aviation Authorities) using JAR (Joint Aviation Regulation) § 25.901(c), § 25.1309.

In August 2005 EASA (European Aviation Safety Agency) published a policy statement on the process for developing instructions for maintenance and inspection of Fuel Tank System ignition source prevention (EASA D 2005/CPRO, www.easa.eu.int/home/cert_policy_statements_en.html) that also included the EASA expectations with regard to compliance times of the corrective actions on the unsafe and the not unsafe part of the harmonised design review results. On a global scale the TC (type certificate) holders committed themselves to the EASA published compliance dates (see EASA policy statement). The EASA policy statement has been revised in March 2006: the date of 31-12-2005 for the unsafe related actions has now been set at 01-07-2006.

Fuel Airworthiness Limitations are items arising from a systems safety analysis that

have been shown to have failure mode(s) associated with an 'unsafe condition' as defined in FAA's memo 2003-112-15 'SFAR 88—Mandatory Action Decision Criteria'. These are identified in Failure Conditions for which an unacceptable probability of ignition risk could exist if specific tasks and/or practices are not performed in accordance with the manufacturers' requirements.

This EASA Airworthiness Directive mandates the Fuel System Airworthiness Limitations (comprising maintenance/inspection tasks and Critical Design Configuration Control Limitations (CDCCL)) for the type of aircraft, that resulted from the design reviews and the JAA recommendation and EASA policy statement mentioned above.

The corrective action is revising the Airworthiness Limitations Section (ALS) of the Instructions for Continued Airworthiness to incorporate new limitations for fuel tank systems.

Restatement of AD 2007-23-05, With No Changes

Actions and Compliance

(f) Unless already done, do the following actions.

(1) Within 3 months after December 11, 2007 (the effective date of AD 2007-23-05), revise the ALS of the Instructions for Continued Airworthiness to incorporate the maintenance and inspection instructions in Part 1 of Saab Fuel Airworthiness Limitations 2000 LKS 009032, dated February 14, 2006. For all tasks identified in Part 1 of Saab Fuel Airworthiness Limitations 2000 LKS 009032, dated February 14, 2006, the initial compliance times start from December 11, 2007, and the repetitive inspections must be accomplished thereafter at the interval specified in Part 1 of Saab Fuel Airworthiness Limitations 2000 LKS 009032, dated February 14, 2006.

(2) Within 12 months after December 11, 2007, revise the ALS of the Instructions for Continued Airworthiness to incorporate the CDCCLs as defined in Part 2 of Saab Fuel Airworthiness Limitations 2000 LKS 009032, dated February 14, 2006.

(3) Except as provided by paragraph (g) of this AD: After accomplishing the actions specified in paragraphs (f)(1) and (f)(2) of this AD, no alternative inspection, inspection intervals, or CDCCLs may be used.

(4) Where Saab Fuel Airworthiness Limitations 2000 LKS 009032, dated February 14, 2006, allows for exceptional short-term extensions, an exception is acceptable to the FAA if it is approved by the appropriate principal inspector in the FAA Flight Standards Certificate Holding District Office.

New Information:

Explanation of CDCCL Requirements

Note 2: Notwithstanding any other maintenance or operational requirements, components that have been identified as airworthy or installed on the affected airplanes before the revision of the airworthiness limitations section (ALS), as required by paragraph (f) of this AD, do not need to be reworked in accordance with the

CDCCLs. However, once the airworthiness limitations section has been revised, future maintenance actions on these components must be done in accordance with the CDCCLs.

FAA AD Differences

Note 3: This AD differs from the MCAI and/or service information as follows: No differences.

Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Shahram Daneshmandi, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-1112; fax (425) 227-1149. Before using any approved AMOC on any airplane to which the AMOC applies, notify your principal maintenance inspector (PMI) or principal avionics inspector (PAI), as appropriate, or lacking a principal inspector, your local Flight Standards District Office. The AMOC approval letter must specifically reference this AD.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements:* For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act, the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Related Information

(h) Refer to MCAI European Aviation Safety Agency Airworthiness Directive 2006-0199, dated July 11, 2006; and Saab Fuel Airworthiness Limitations 2000 LKS 009032, dated February 14, 2006; for related information.

Material Incorporated by Reference

(i) You must use Saab Fuel Airworthiness Limitations 2000 LKS 009032, dated February 14, 2006, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register previously approved the incorporation by reference of this service information on December 11, 2007 (72 FR 62564, November 6, 2007).

(2) For service information identified in this AD, contact Saab Aircraft AB, SAAB Aerosystems, SE 581 88, Linköping, Sweden; telephone +46 13 18 5591; fax +46 13 18 4874; e-mail saab2000.techsupport@saabgroup.com; Internet <http://www.saabgroup.com>.

(3) You may review copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221 or 425-227-1152.

(4) You may also review copies of the service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on September 18, 2009.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E9-24542 Filed 10-14-09; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF COMMERCE

Bureau of Industry and Security

15 CFR Parts 730, 734, 738, 740, 742, 744, 772 and 774

[Docket No. 080211163-9110-02]

RIN 0694-AE18

Encryption Simplification Rule: Final

AGENCY: Bureau of Industry and Security, Commerce.

ACTION: Final rule.

SUMMARY: The Bureau of Industry and Security (BIS) published the interim final rule entitled "Encryption Simplification" on October 3, 2008 (73 FR 57495). This rule finalizes that rule, corrects errors published in the October 3, 2008 interim final rule, and resolves inconsistencies in that rule identified by the public.

DATES: *Effective Dates:* This rule is effective October 15, 2009.

ADDRESSES: Written comments on this final rule may be sent by e-mail to publiccomments@bis.doc.gov. Include "Encryption rule" in the subject line of the message. Comments may also be submitted by mail or hand delivery to Sharron Cook, Office of Exporter Services, Regulatory Policy Division, Bureau of Industry and Security, Department of Commerce, 14th St. & Pennsylvania Avenue, NW., Room 2705, Washington, DC 20230, ATTN: Encryption rule; or by fax to (202) 482-3355.

FOR FURTHER INFORMATION CONTACT: For questions of a general nature contact Sharron Cook, Office of Exporter Services, Regulatory Policy Division at

(202) 482-2440 or e-mail: scook@bis.doc.gov.

For questions of a technical nature contact: The Information Technology Division, Office of National Security and Technology Transfer Controls at 202-482-0707 or e-mail: C. Randall Pratt at cpratt@bis.doc.gov.

SUPPLEMENTARY INFORMATION:

Background

BIS published the interim final rule entitled "Encryption Simplification" on October 3, 2008 (73 FR 57495). This rule removed section 744.9 of the EAR, which set forth requirements for authorization from BIS for U.S. persons to provide technical assistance (including training) to foreign persons with the intent to aid a foreign person in the development or manufacture outside the United States of encryption commodities or software that, if of U.S.-origin, would be "EI" controlled under ECCNs 5A002 or 5D002. Section 744.9 was added to the EAR in 1996 when jurisdiction over dual-use encryption items was transferred from the Department of State to the Department of Commerce. However, other parts of the EAR that referred to section 744.9 were inadvertently not removed. Therefore, this rule removes these references in § 730.5(d), § 734.5(c), § 736.2(b)(7)(ii), and § 744.1(a)(1). In addition, other corrections are made to harmonize with revisions made in the "Encryption Simplification" rule published on October 3, 2008. Some of the revisions in this rule are the results of requests for clarification from the public on the October 3 encryption simplification rule.

Part 730

The last sentence in paragraph (d) of section 730.5 is removed, because it makes reference to technical assistance in section 744.9, which was removed by the October 3 encryption simplification rule.

Part 734

Section 734.4 is amended to revise paragraphs (b)(1) and (b)(2) in order to harmonize with the October 3 encryption simplification rule and corrections thereto. Paragraph (b)(1)(iv) is added to conform with the clarifications in this correction by making it clear that section 740.17(b)(4) is a separate authorization. Paragraph (b)(2) is revised to simply state that all items classified under ECCNs 5A992, 5D992, or 5E992 are eligible for consideration under the *de minimis* rules. Paragraph (c) of section 734.5 is removed because it refers to technical assistance in section 744.9, which was