

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new AD:

Empresa Brasileira de Aeronautica S.A. (EMBRAER): Docket No. FAA-2010-0754; Directorate Identifier 2010-CE-039-AD.

Comments Due Date

(a) We must receive comments by September 17, 2010.

Affected ADs

(b) None.

Applicability

(c) This AD applies to Model EMB-500 airplanes, serial numbers 50000005 through 50000134, 50000136, 50000137, and 50000139 through 50000165, certificated in any category.

Subject

(d) Air Transport Association of America (ATA) Code 27: Flight Controls.

Reason

(e) The mandatory continuing airworthiness information (MCAI) states:

It has been found that certain regions of the elevators, elevators trim tabs, and ailerons do not present drain holes to avoid water accumulation inside of these flight control surfaces. Internal water accumulation may lead to flight control surfaces unbalancing possibly reducing the flutter margins, which could result in loss of airplane control.

Since this condition may occur in other airplanes of the same type and affects flight safety, a corrective action is required. Thus, sufficient reason exists to request compliance with this AD in the indicated time limit.

The MCAI requires you to drill new drain holes in the elevators, elevators trim tabs, and ailerons surfaces. You may obtain further information by examining the MCAI in the AD docket.

Actions and Compliance

(f) Unless already done, within the next 24 calendar months after the effective date of this AD, rework the elevators, elevators trim tabs, and ailerons surfaces by drilling additional drain holes in them following Empresa Brasileira de Aeronautica S.A. (EMBRAER) Service Bulletin 500-57-0001, dated April 28, 2010.

FAA AD Differences

Note: This AD differs from the MCAI and/or service information as follows: No differences.

Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, Standards Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Karl Schletzbaum, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri

64106; telephone: (816) 329-4146; fax: (816) 329-4090. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements:* For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act (44 U.S.C. 3501 *et seq.*), the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Related Information

(h) Refer to MCAI AGÊNCIA NACIONAL DE AVIAÇÃO CIVIL—BRAZIL (ANAC), AD No.: 2010-07-01, dated August 9, 2010; and Empresa Brasileira de Aeronautica S.A. (EMBRAER) Service Bulletin 500-57-0001, dated April 28, 2010, for related information.

Issued in Kansas City, Missouri, on July 26, 2010.

Christina L. Marsh,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2010-19019 Filed 8-2-10; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2010-0755; Directorate Identifier 2010-NE-12-AD]

RIN 2120-AA64

Airworthiness Directives; Rolls-Royce plc (RR) RB211-Trent 800 Series Turbofan Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for the products listed above. This proposed AD results from mandatory continuing airworthiness information (MCAI) issued by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

Revision of the Critical Part lives has been necessary due to actual operational flight

profiles not conforming to those assumed at entry into service and is associated with a revised Flight Profile Monitoring methodology (originally based on engine thrust rating but now based on operating shaft speeds) introduced by Rolls-Royce.

The new Flight Profile Monitoring methodology allows for seven new profiles replacing the previous three. Six of these profiles, A to F, are intended to cover the requirements of most operators. The Declared Life (in Standard Duty Cycles) is published for each part and life usage may be accounted by factoring the number of flights flown. The factor to be used is defined according to the Flight Profile which is applicable to the fleet.

The seventh profile, called "Heavy", will be applicable to fleets operating outside profiles A to F. A separate Declared Life (in Flight Cycles) is published for each part and life usage is accounted without factoring.

We are proposing this AD to prevent failure of critical rotating parts from exceeding the new, lower life limits, which could result in uncontained failure of the engine and damage to the airplane.

DATES: We must receive comments on this proposed AD by September 17, 2010.

ADDRESSES: You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov> and follow the instructions for sending your comments electronically.

- *Mail:* Docket Management Facility, U.S. Department of Transportation, 1200 New Jersey Avenue, SE., West Building Ground Floor, Room W12-140, Washington, DC 20590-0001.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

- *Fax:* (202) 493-2251.

Contact Rolls-Royce plc, P.O. Box 31, Derby, DE24 8BJ, United Kingdom: Telephone 44 (0) 1332 242424; fax 44 (0) 1332 249936, for the service information identified in this proposed AD.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone (800) 647-5527) is the same as the Mail address provided in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT:

James Lawrence, Aerospace Engineer, Engine Certification Office, FAA, Engine and Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803; e-mail: james.lawrence@faa.gov; telephone (781) 238-7176; fax (781) 238-7199.

SUPPLEMENTARY INFORMATION:**Comments Invited**

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2010-0755; Directorate Identifier 2010-NE-12-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD based on those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact with FAA personnel concerning this proposed AD. Using the search function of the Web site, anyone can find and read the comments in any of our dockets, including, if provided, the name of the individual who sent the comment (or signed the comment on behalf of an association, business, labor union, etc.). You may review the DOT's complete Privacy Act Statement in the **Federal Register** published on April 11, 2000 (65 FR 19477-78).

Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued EASA Airworthiness Directive 2007-0003R1, dated January 15, 2009 (referred to after this as "the MCAI"), to correct an unsafe condition for the specified products. The MCAI states:

The MCAI describes the unsafe condition as:

Revision of the Critical Part lives has been necessary due to actual operational flight profiles not conforming to those assumed at entry into service and is associated with a revised Flight Profile Monitoring methodology (originally based on engine thrust rating but now based on operating shaft speeds) introduced by Rolls-Royce.

The new Flight Profile Monitoring methodology allows for seven new profiles replacing the previous three. Six of these profiles, A to F, are intended to cover the requirements of most operators. The Declared Life (in Standard Duty Cycles) is published

for each part and life usage may be accounted by factoring the number of flights flown. The factor to be used is defined according to the Flight Profile which is applicable to the fleet.

The seventh profile, called "Heavy", will be applicable to fleets operating outside profiles A to F. A separate Declared Life (in Flight Cycles) is published for each part and life usage is accounted without factoring.

You may obtain further information by examining the MCAI in the AD docket.

Relevant Service Information

Rolls-Royce plc has issued RB211 Trent 800 Series Propulsion System Non-Modification Service Bulletin Alert RB.211-72-AE935, Revision 7, dated January 19, 2009. The actions described in this service information are intended to correct the unsafe condition identified in the MCAI.

FAA's Determination and Requirements of This Proposed AD

This product has been approved by the aviation authority of the United Kingdom, and is approved for operation in the United States. Pursuant to our bilateral agreement with the United Kingdom, they have notified us of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all information provided by EASA, and determined the unsafe condition exists and is likely to exist or develop on other products of the same type design.

Differences Between This AD and the MCAI or Service Information

The MCAI requires incorporating the revised Trent 800 life limits no later than January 31, 2007. This proposed AD would require incorporating the revised Trent 800 life limits within 30 days after the effective date of this proposed AD.

Costs of Compliance

Based on the service information, we estimate that this proposed AD would affect about 16 products of U.S. registry. The average labor rate is \$85 per work-hour; there is no labor cost because disks are replaced at scheduled maintenance intervals. Prorated cost of parts would cost about \$45,000 per product. Based on these figures, we estimate the cost of the proposed AD on U.S. operators to be \$720,000.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more

detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new AD:

Rolls-Royce plc: Docket No. FAA-2010-0755; Directorate Identifier 2010-NE-12-AD.

Comments Due Date

(a) We must receive comments by September 17, 2010.

Affected Airworthiness Directives (ADs)

(b) None.

Applicability

(c) This AD applies to Rolls-Royce plc RB211-Trent 895-17, 892-17, 892B-17, 884-17, 884B-17, 877-17 and 875-17 turbofan engines. These engines are installed on, but not limited to, Boeing 777 series airplanes.

Reason

(d) This AD results from:

Revision of the Critical Part lives has been necessary due to actual operational flight profiles not conforming to those assumed at entry into service and is associated with a revised Flight Profile Monitoring methodology (originally based on engine thrust rating but now based on operating shaft speeds) introduced by Rolls-Royce.

The new Flight Profile Monitoring methodology allows for seven new profiles replacing the previous three. Six of these profiles, A to F, are intended to cover the requirements of most operators. The Declared Life (in Standard Duty Cycles) is published for each part and life usage may be accounted by factoring the number of flights flown. The factor to be used is defined according to the Flight Profile which is applicable to the fleet.

The seventh profile, called "Heavy", will be applicable to fleets operating outside profiles A to F. A separate Declared Life (in Flight Cycles) is published for each part and life usage is accounted without factoring.

This AD is necessary as life reductions are applicable in some cases and failure to comply with the revised life limits could result in an unsafe condition.

We are issuing this AD to prevent failure of critical rotating parts from exceeding the new, lower life limits, which could result in uncontained failure of the engine and damage to the airplane.

Actions and Compliance

(e) Compliance is required within 30 days after the effective date of this AD, unless already done, do the following actions.

(1) Revise the airworthiness limitations section (ALS) of your instructions for continued airworthiness (ICA) to incorporate Task 05-10-01-800-801, "Critical and Critical Group A Parts Lives—Multiple Flight Profile Monitoring" and Task 05-10-01-800-802, "Critical and Critical Group A Parts Lives in the HEAVY Flight Profile" of the Rolls-Royce Trent 800 Time Limits manual (TLM) dated June 15, 2009.

(2) Thereafter, do not revise the ALS of your ICA by incorporating any revision of the Rolls-Royce Trent 800 TLM dated prior to the June 15, 2009 revision.

FAA AD Differences

(f) This AD differs from the Mandatory Continuing Airworthiness Information (MCAI) and or service information as follows:

(1) The MCAI AD requires revising the airworthiness limitations section no later than January 31, 2007. This AD requires revising the airworthiness limitations section

within 30 days after the effective date of this AD.

(2) This AD prohibits incorporating into the ALS of the ICA, any revision of the Rolls-Royce Trent 800 TLM earlier than the June 15, 2009.

Other FAA AD Provisions

(g) *Alternative Methods of Compliance (AMOCs)*: The Manager, Engine Certification Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19.

Related Information

(h) Refer to MCAI EASA Airworthiness Directive 2007-0003R1, dated January 15, 2009, and Rolls-Royce plc RB211 Trent 800 Series Propulsion System Non-Modification Service Bulletin Alert RB.211-72-AE935, Revision 7, dated January 19, 2009, for related information. Contact Rolls-Royce plc, P.O. Box 31, Derby, DE24 8BJ, United Kingdom: telephone 044 1332 242424; fax 044 1332 249936, for a copy of this service information.

(i) Contact James Lawrence, Aerospace Engineer, Engine Certification Office, FAA, Engine and Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803; e-mail: james.lawrence@faa.gov; telephone (781) 238-7176; fax (781) 238-7199, for more information about this AD.

Issued in Burlington, Massachusetts, on July 19, 2010.

Thomas A. Boudreau,

Acting Manager, Engine and Propeller Directorate, Aircraft Certification Service.

[FR Doc. 2010-19027 Filed 8-2-10; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Office of the Secretary****14 CFR Parts 234, 244, 250, 253, 259, and 399**

[Docket No. DOT-OST-2010-0140]

RIN No. 2105-AD92

Enhancing Airline Passenger Protections

AGENCY: Office of the Secretary (OST), Department of Transportation (DOT).

ACTION: Extension of comment period on proposed rule.

SUMMARY: This action extends the comment period for an NPRM on enhancing airline passenger protections that was published in the **Federal Register** on June 8, 2010. The Department of Transportation is extending the period for interested persons to submit comments on this rulemaking from August 9, 2010, to September 23, 2010. This extension is a result of requests from a number of airline associations, one airport

association, and two airlines to extend the comment period for the proposal.

DATES: Comments must be received by September 23, 2010. Comments received after this date will be considered to the extent practicable.

ADDRESSES: You may file comments identified by the docket number DOT-OST-2010-0140 by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov> and follow the online instructions for submitting comments.

- *Mail:* Docket Management Facility, U.S. Department of Transportation, 1200 New Jersey Ave., SE., Room W12-140, Washington, DC 20590-0001.

- *Hand Delivery or Courier:* West Building Ground Floor, Room W12-140, 1200 New Jersey Ave., SE., between 9 a.m. and 5 p.m. ET, Monday through Friday, except Federal Holidays.

- *Fax:* (202) 493-2251.

Instructions: You must include the agency name and docket number DOT-OST-2010-0140 or the Regulatory Identification Number, RIN No. 2105-AD92, for the rulemaking at the beginning of your comment. All comments received will be posted without change to <http://www.regulations.gov>, including any personal information provided.

Privacy Act: Anyone is able to search the electronic form of all comments received in any of our dockets by the name of the individual submitting the comment (or signing the comment if submitted on behalf of an association, a business, a labor union, etc.). You may review DOT's complete Privacy Act statement in the **Federal Register** published on April 11, 2000 (65 FR 19477-78), or you may visit <http://DocketsInfo.dot.gov>.

Docket: For access to the docket to read background documents or comments received, go to <http://www.regulations.gov> or to the street address listed above. Follow the online instructions for accessing the docket.

FOR FURTHER INFORMATION CONTACT: Blane A. Workie or Daeleen Chesley, Office of the Assistant General Counsel for Aviation Enforcement and Proceedings, U.S. Department of Transportation, 1200 New Jersey Ave., SE., Washington, DC 20590, 202-366-9342 (phone), 202-366-7152 (fax), blane.workie@dot.gov or daeleen.chesley@dot.gov (e-mail).

SUPPLEMENTARY INFORMATION: On June 8, 2010, the Department published a Notice of Proposed Rulemaking (NPRM) on enhancing airline passenger protections that proposed to improve the air travel environment for