

TABLE 1—PREVIOUS SERVICE INFORMATION

Bombardier Service Bulletin—	Revision—	Dated—
8–32–166	Original	April 14, 2008.
8–32–166	A	January 29, 2009.
84–32–57	Original	April 30, 2008.

FAA AD Differences

Note 1: This AD differs from the MCAI and/or service information as follows: No differences.

Other FAA AD Provisions

(i) The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, New York Aircraft Certification Office, ANE–170, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO, 1600 Stewart Avenue, Suite 410, Westbury, New York, 11590; telephone 516–228–7300; fax 516–794–5531. Before using any approved AMOC on any airplane to which the AMOC applies, notify your principal maintenance inspector (PMI) or principal avionics inspector (PAI), as appropriate, or lacking a principal inspector, your local Flight Standards District Office. The AMOC approval letter must specifically reference this AD.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements:* For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act (44 U.S.C. 3501 *et seq.*), the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120–0056.

Related Information

(j) Refer to MCAI Canadian Airworthiness Directive CF–2009–46, dated December 14, 2009; Bombardier Service Bulletin 8–32–166, Revision B, dated March 2, 2010; and Bombardier Service Bulletin 84–32–57, Revision A, dated June 15, 2009; for related information.

Material Incorporated by Reference

(k) You must use Bombardier Service Bulletin 84–32–57, Revision A, dated June 15, 2009; or Bombardier Service Bulletin 8–32–166, Revision B, dated March 2, 2010; as applicable; to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Bombardier, Inc., 400 Côte-

Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514–855–5000; fax 514–855–7401; e-mail thd.qseries@aero.bombardier.com; Internet <http://www.bombardier.com>.

(3) You may review copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, Washington. For information on the availability of this material at the FAA, call 425–227–1221.

(4) You may also review copies of the service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202–741–6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on September 23, 2010.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2010–25016 Filed 10–6–10; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA–2010–0639; Directorate Identifier 2009–NM–232–AD; Amendment 39–16463; AD 2010–21–03]

RIN 2120–AA64

Airworthiness Directives; McDonnell Douglas Corporation Model DC–8–31, DC–8–32, DC–8–33, DC–8–41, DC–8–42, and DC–8–43 Airplanes; Model DC–8–50 Series Airplanes; Model DC–8F–54 and DC–8F–55 Airplanes; Model DC–8–60 Series Airplanes; Model DC–8–60F Series Airplanes; Model DC–8–70 Series Airplanes; and Model DC–8–70F Series Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: The FAA is superseding an existing airworthiness directive (AD) that applies to all of the McDonnell Douglas Corporation airplanes identified above. The existing AD currently requires revising the

maintenance program to incorporate new airworthiness limitations for fuel tank systems to satisfy Special Federal Aviation Regulation No. 88 requirements. This new AD adds requirements to revise the maintenance program to incorporate specific Critical Design Configuration Control Limitations (CDCCL) information and install fuel tank float switch in-line fuses. This new AD also adds two Airworthiness Limitations inspections (ALIs). This AD results from a design review of the fuel tank systems. We are issuing this AD to prevent the potential for ignition sources inside fuel tanks caused by latent failures, alterations, repairs, or maintenance actions, which, in combination with flammable fuel vapors, could result in a fuel tank explosion and consequent loss of the airplane.

DATES: This AD becomes effective November 12, 2010.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in the AD as of November 12, 2010.

On May 27, 2008 (73 FR 21523, April 22, 2008), the Director of the Federal Register approved the incorporation by reference of a certain other publication listed in the AD.

ADDRESSES: For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, 3855 Lakewood Boulevard, MC D800–0019, Long Beach, California 90846–0001; telephone 206–544–5000, extension 2; fax 206–766–5683; e-mail dse.boecom@boeing.com; Internet <https://www.myboeingfleet.com>.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The address for the Docket Office (telephone 800–647–5527) is the Document Management Facility, U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140,

1200 New Jersey Avenue, SE., Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Samuel Lee, Aerospace Engineer, Propulsion Branch, ANM-140L, FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California 90712-4137; telephone (562) 627-5262; fax (562) 627-5210.

SUPPLEMENTARY INFORMATION:

Discussion

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that supersedes AD 2008-09-04, Amendment 39-15484 (73 FR 21523, April 22, 2008). The existing AD applies to all Model DC-8-31, DC-8-32, DC-8-33, DC-8-41, DC-8-42, and DC-8-43 airplanes; Model DC-8-50 series airplanes; Model DC-8F-54 and DC-8F-55 airplanes; Model DC-8-60 series airplanes; Model DC-8-60F series airplanes; Model DC-8-70 series airplanes; and Model DC-8-70F series airplanes. That NPRM was published in the **Federal Register** on June 25, 2010 (75 FR 36298). That NPRM proposed to continue to require revising the

maintenance program. That NPRM also proposed to add requirements to revise the maintenance program to incorporate specific Critical Design Configuration Control Limitations (CDCCL) information and install fuel tank float switch in-line fuses. That NPRM also proposed to add two Airworthiness Limitations inspections (ALIs).

Relevant Service Information

We reviewed Boeing DC-8 Special Compliance Item Report, MDC-02K9030, Revision D, dated June 9, 2010. This service information does not add any additional work. We have revised paragraphs (j), (m), and (n) of this AD to refer to this report.

Comments

We provided the public the opportunity to participate in the development of this AD. No comments have been received on the NPRM or on the determination of the cost to the public.

Change to Paragraph Reference

We revised paragraph (l) of this AD to correct a typographical error that appeared in the NPRM. In paragraph (l) of the NPRM, we inadvertently referred

to “paragraph (k)” instead of “paragraph (j)” of the AD. Paragraph (l) of this final rule correctly references paragraph (j) of this AD.

Explanation of Additional Change to NPRM

We also clarified the airplanes affected by paragraph (k) of this AD by referring to the airplanes identified in Boeing Service Bulletin DC8-28-090, dated October 9, 2009. Airplanes not listed in the effectivity of Boeing Service Bulletin DC8-28-090, dated October 9, 2009, are not required to do the installation required by paragraph (k) of this AD.

Conclusion

We have carefully reviewed the available data and determined that air safety and the public interest require adopting the AD with the changes mentioned previously.

Costs of Compliance

There are about 125 airplanes of the affected design in the worldwide fleet. The following table provides the estimated costs for U.S. operators to comply with this AD.

ESTIMATED COSTS

Action	Work hours	Average labor rate per hour	Parts	Cost per airplane	Number of U.S.-registered airplanes	Fleet cost
Revising the Maintenance Program (required by AD 2008-09-04).	1	\$85	\$0	\$85	125	\$10,625.
Revising the Airworthiness Limitation Section (new action).	1	85	0	\$85	125	\$10,625.
Installing fuses (new action)	Up to 35 hours	85	0	Up to \$2,975	125	Up to \$371,875.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in subtitle VII, part A, subpart III, section 44701, “General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We have determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:
 (1) Is not a “significant regulatory action” under Executive Order 12866;
 (2) Is not a “significant rule” under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
 (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.
 We prepared a regulatory evaluation of the estimated costs to comply with

this AD and placed it in the AD docket. See the **ADDRESSES** section for a location to examine the regulatory evaluation.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

■ Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The Federal Aviation Administration (FAA) amends § 39.13 by removing Amendment 39–15484 (73 FR 21523, April 22, 2008) and by adding the following new airworthiness directive (AD):

2010–21–03 McDonnell Douglas

Corporation: Amendment 39–16463. Docket No. FAA–2010–0639; Directorate Identifier 2009–NM–232–AD.

Effective Date

(a) This AD becomes effective November 12, 2010.

Affected ADs

(b) This AD supersedes AD 2008–09–04, Amendment 39–15484.

Applicability

(c) This AD applies to all McDonnell Douglas Model DC–8–31, DC–8–32, DC–8–33, DC–8–41, DC–8–42, and DC–8–43 airplanes; Model DC–8–51, DC–8–52, DC–8–53, and DC–8–55 airplanes; Model DC–8F–54 and DC–8F–55 airplanes; Model DC–8–61, DC–8–62, and DC–8–63 airplanes; Model DC–8–61F, DC–8–62F, and DC–8–63F airplanes; Model DC–8–71, DC–8–72, and DC–8–73 airplanes; and Model DC–8–71F, DC–8–72F, and DC–8–73F airplanes; certificated in any category.

Note 1: This AD requires revisions to certain operator maintenance documents to include new inspections. Compliance with these inspections is required by 14 CFR 91.403(c). For airplanes that have been previously modified, altered, or repaired in the areas addressed by these inspections, the operator may not be able to accomplish the inspections described in the revisions. In this situation, to comply with 14 CFR 91.403(c), the operator must request approval for an alternative method of compliance (AMOC) in accordance with paragraph (o) of this AD. The request should include a description of changes to the required inspections that will ensure the continued operational safety of the airplane.

Subject

(d) Air Transport Association (ATA) of America Code 28: Fuel.

Unsafe Condition

(e) This AD results from a design review of the fuel tank systems. The Federal Aviation Administration is issuing this AD to prevent the potential for ignition sources inside fuel tanks caused by latent failures, alterations, repairs, or maintenance actions, which, in combination with flammable fuel vapors, could result in a fuel tank explosion and consequent loss of the airplane.

Compliance

(f) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Restatement of Requirements of AD 2008–09–04, With Revised Compliance Method

Revise the Maintenance Program

(g) Before December 16, 2008, revise the maintenance program to incorporate the information specified in Appendixes B, C, and D of the Boeing DC–8 Special Compliance Item Report, MDC–02K9030, Revision A, dated August 8, 2006.

No Reporting Requirement

(h) Although the Boeing DC–8 Special Compliance Item Report, MDC–02K9030, Revision A, dated August 8, 2006, specifies to submit certain information to the manufacturer, this AD does not require that action.

No Alternative Inspections, Inspection Intervals, or Critical Design Configuration Control Limitations (CDCCLs)

(i) Except as provided by paragraph (m) of this AD, after accomplishing the applicable actions specified in paragraph (g) of this AD, no alternative inspections, inspection intervals, or CDCCLs may be used unless the inspections, intervals, or CDCCLs are approved as an AMOC in accordance with the procedures specified in paragraph (o) of this AD.

New Requirements of This AD

Revise the Maintenance Program

(j) Within 30 days after the effective date of this AD, revise the maintenance program to incorporate the information required by paragraphs (j)(1), (j)(2), and (j)(3) of this AD.

(1) CDCCL 20–10, “DC–8 Float Switch Circuit” in Appendix B of Boeing DC–8 Special Compliance Item Report, MDC–02K9030, Revision C, dated January 5, 2010; or Revision D, dated June 9, 2010.

(2) ALI 30–1 “DC–8 Pneumatic System Decay Check” in Appendix C of Boeing DC–8 Special Compliance Item Report, MDC–02K9030, Revision C, dated January 5, 2010; or Revision D, dated June 9, 2010.

(3) ALI 28–1, “DC–8 Alternate and Center Auxiliary Tank Fuel Pump Control Systems Check,” in Appendix C of Boeing DC–8 Special Compliance Item Report, MDC–02K9030, Revision C, dated January 5, 2010; or Revision D, dated June 9, 2010.

Install the In-Line Fuses

(k) For airplanes identified in Boeing Service Bulletin DC8–28–090, dated October 9, 2009: Within 60 months after the effective date of this AD, install the fuel tank float switch in-line fuses in the leading edges of

the front spars of the left and right wings, in accordance with the Accomplishment Instructions of Boeing Service Bulletin DC8–28–090, dated October 9, 2009.

No Alternative Inspections, Inspection Intervals, or Critical Design Configuration Control Limitations (CDCCLs)

(l) After accomplishing the actions specified in paragraph (j) of this AD, no alternative inspections, inspection intervals, or CDCCLs may be used unless the inspections, intervals, or CDCCLs are approved as an AMOC in accordance with the procedures specified in paragraph (o) of this AD.

(m) Revising the maintenance program to incorporate the information specified in Appendixes B, C, and D of the Boeing DC–8 Special Compliance Item Report, MDC–02K9030, Revision B, dated July 23, 2009; Revision C, dated January 5, 2010; or Revision D, dated June 9, 2010; is acceptable for compliance with the actions specified in paragraph (g) of this AD.

No Reporting Requirement

(n) Although the Boeing DC–8 Special Compliance Item Report, MDC–02K9030, Revision B, dated July 23, 2009; Revision C, dated January 5, 2010; and Revision D, dated June 9, 2010; specify to submit certain information to the manufacturer, this AD does not require that action.

Alternative Methods of Compliance (AMOCs)

(o)(1) The Manager, Los Angeles Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Samuel Lee, Aerospace Engineer, Propulsion Branch, ANM–140L, FAA, Los Angeles Aircraft Certification Office (ACO), 3960 Paramount Boulevard, Lakewood, California 90712–4137; telephone (562) 627–5262; fax (562) 627–5210.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your principal maintenance inspector (PMI) or principal avionics inspector (PAI), as appropriate, or lacking a principal inspector, your local Flight Standards District Office. The AMOC approval letter must specifically reference this AD.

Material Incorporated by Reference

(p) You must use the applicable service information contained in Table 1 of this AD to do the actions required by this AD, unless the AD specifies otherwise.

TABLE 1—ALL MATERIAL INCORPORATED BY REFERENCE

Document	Revision	Date
Boeing DC–8 Special Compliance Item Report, MDC–02K9030	A	August 8, 2006.
Boeing DC–8 Special Compliance Item Report, MDC–02K9030	B	July 23, 2009.
Boeing DC–8 Special Compliance Item Report, MDC–02K9030	C	January 5, 2010.
Boeing DC–8 Special Compliance Item Report, MDC–02K9030	D	June 9, 2010.

TABLE 1—ALL MATERIAL INCORPORATED BY REFERENCE—Continued

Document	Revision	Date
Boeing Service Bulletin DC8–28–090	Original	October 9, 2009.

Boeing DC–8 Special Compliance Item Report, MDC–02K9030, Revision B, dated July 23, 2009, contains the following effective pages:

LIST OF EFFECTIVE PAGES

Page title/description	Page number(s)	Revision number	Date shown on Page(s)
Report Title Page	None shown	B	July 23, 2009.
Index of Page Changes	ii, iii	B	None shown.*
Table of Contents	iv, v	B	None shown.*
Discussion	1	New	None shown.*
Appendix A	A1–A4	New	None shown.*
Appendix B	B1, B3, B4, B6–B12	New	None shown.*
	B2, B5, B13–B24	B	None shown.*
Appendix C	C1–C5	New	None shown.*
	C6–C10	B	None shown.*
Appendix D	D1	New	None shown.*

Boeing DC–8 Special Compliance Item Report, MDC–02K9030, Revision C, dated January 5, 2010, contains the following effective pages:

LIST OF EFFECTIVE PAGES

Page title/description	Page number(s)	Revision number	Date shown on page(s)
Report Title Page	None shown	C	January 5, 2010.
Index of Page Changes	ii, iii	C	None shown.*
Table of Contents	iv, v	C	None shown.*
Discussion	1	C	None shown.*
Appendix A	A1–A3	New	None shown.*
	A4–A25	C	None shown.*
Appendix B	B1, B3, B4, B6–B12	New	None shown.*
	B2, B5, B13–B24	B	None shown.*
Appendix C	C1–C5	New	None shown.*
	C6–C10	B	None shown.*
	C11–C14	C	None shown.*
Appendix D	D1	New	None shown.*

Boeing DC–8 Special Compliance Item Report, MDC–02K9030, Revision D, dated June 9, 2010, contains the following effective pages:

LIST OF EFFECTIVE PAGES

Page title/description	Page number(s)	Revision number	Date shown on page(s)
Report Title Page	None shown	D	June 9, 2010.
Attachment A	None shown	None shown	June 22, 2010.
Index of Page Changes	ii	B	None shown.*
	iii	C	None shown.*
Table of Contents	iv, v	C	None shown.*
Discussion	1	C	None shown.*
Appendix A	A1–A3	New	None shown.*
	A4–A25	C	None shown.*
Appendix B	B1, B3, B6, B7, B9, B12	New	None shown.*
	B2, B13–B24	B	None shown.*
	B4, B5, B8, B10, B11	D	None shown.*
Appendix C	C1–C5	New	None shown.*
	C6–C10	B	None shown.*
	C11–C14	C	None shown.*
Appendix D	D1	New	None shown.*

(* The revision date of these documents is shown only on the title page of these documents.)

(1) The Director of the Federal Register approved the incorporation by reference of the service information contained in Table 2

of this AD under 5 U.S.C. 552(a) and 1 CFR part 51.

TABLE 2—NEW MATERIAL INCORPORATED BY REFERENCE

Document	Revision	Date
Boeing DC-8 Special Compliance Item Report, MDC-02K9030	B	July 23, 2009.
Boeing DC-8 Special Compliance Item Report, MDC-02K9030	C	January 5, 2010.
Boeing DC-8 Special Compliance Item Report, MDC-02K9030	D	June 9, 2010.
Boeing Service Bulletin DC8-28-090	Original	October 9, 2009.

(2) The Director of the Federal Register previously approved the incorporation by reference of Boeing DC-8 Special Compliance Item Report, MDC-02K9030, Revision A, dated August 8, 2006, on May 27, 2008 (73 FR 21523, April 22, 2008).

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, 3855 Lakewood Boulevard, MC D800-0019, Long Beach, California 90846-0001; telephone 206-544-5000, extension 2; fax 206-766-5683; e-mail dse.boecom@boeing.com; Internet <https://www.myboeingfleet.com>.

(4) You may review copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may also review copies of the service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on September 23, 2010.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2010-25021 Filed 10-6-10; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA-2010-0808; Airspace Docket No. 10-AWP-14]

RIN 2120-AA66

Amendment of Class E Airspace; Kwajalein Island, Marshall Islands, RMI

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule, technical amendment.

SUMMARY: This action removes the reference to the Kwajalein Tactacial Air

Navigation (TACAN) System from the legal description of the Class E airspace areas for Kwajalein Island, Bucholz AAF, Marshall Islands, RMI. The U.S. Army notified the FAA that the Kwajalein TACAN was decommissioned. This action corrects the legal descriptions for the Class E airspace areas in the vicinity of the Marshall Islands.

DATES: Effective date 0901 UTC, January 13, 2011. The Director of the Federal Register approves this incorporation by reference action under 1 CFR part 51, subject to the annual revision of FAA Order 7400.9 and publication of conforming amendments.

FOR FURTHER INFORMATION CONTACT: Ken McElroy, Airspace and Rules Group, Office of System Operations Airspace and AIM, Federal Aviation Administration, 800 Independence Avenue, SW., Washington, DC 20591; telephone: (202) 267-8783.

SUPPLEMENTARY INFORMATION:

The Rule

This action amends Title 14 Code of Federal Regulations (14 CFR) part 71 by removing the reference to the Kwajalein TACAN, as it has been decommissioned, from the legal description of Class E airspace designated as an extension to a Class D surface area, and Class E airspace areas extending upward from 700 feet or more above the surface of the earth at Kwajalein Island, Bucholz AAF, Marshall Islands, RMI. Therefore, notice and public procedures under 5 U.S.C. 553(b) are unnecessary.

Class E airspace designations are published in paragraphs 6004 and 6005 of FAA Order 7400.9U signed August 18, 2010, and effective September 15, 2010, which is incorporated by reference in 14 CFR 71.1. The Class E airspace designations listed in this document will be published subsequently in the Order.

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally

current. Therefore, this regulation: (1) Is not a “significant regulatory action” under Executive Order 12866; (2) is not a “significant rule” under Department of Transportation (DOT) Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this rule, when promulgated, will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

The FAA’s authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency’s authority.

This rulemaking is promulgated under the authority described in subtitle VII, part A, subpart I, section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of the airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it amends Class E airspace at Kwajalein Island, Marshall Island, RMI.

Environmental Review

The FAA has determined that this action qualifies for categorical exclusion under the National Environmental Policy Act in accordance with 311a., FAA Order 1050.1E, “Environmental Impacts: Policies and Procedures.” This airspace action is not expected to cause any potentially significant environmental impacts, and no extraordinary circumstances exist that warrant preparation of an environmental assessment.

List of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (air).