

TABLE 2—ALL MATERIAL INCORPORATED BY REFERENCE—Continued

Service information	Date
BAE Systems (Operations) Limited Service Bulletin J41-11-027	March 29, 2007.

BAE Systems (Operations) Limited Aircraft Change Information Bulletin J41-61-014, Section 2, Issue 7, contains the following effective pages:

LIST OF EFFECTIVE PAGES

Page title/description	Page number(s)	Issue number	Date shown on page(s)
Section 2, Installer Instructions	15-50	7	August 17, 2009.

(Section 1 of this document (pages 1-14) is not included.)
 (1) The Director of the Federal Register approved the incorporation by reference of BAE Systems (Operations) Limited Aircraft Change Information Bulletin J41-61-014, Section 2, Issue 7, dated August 17, 2009, under 5 U.S.C. 552(a) and 1 CFR part 51.
 (2) The Director of the Federal Register previously approved the incorporation by reference of the service information contained in Table 3 of this AD on July 24, 2008 (73 FR 34847, June 19, 2008).

TABLE 3—MATERIAL PREVIOUSLY INCORPORATED BY REFERENCE

Service information	Date
BAE Jetstream Series 4100 Advance Amendment Bulletin 13 to the Jetstream Series 4100 Flight Manual	April 4, 2007.
BAE Jetstream Series 4100 General Amendment G12 to the Jetstream Series 4100 Flight Manual	January 2007.
BAE Systems (Operations) Limited Service Bulletin J41-11-027	March 29, 2007.

(3) For service information identified in this AD, contact BAE Systems (Operations) Limited, Customer Information Department, Prestwick International Airport, Ayrshire, KA9 2RW, Scotland, United Kingdom; telephone +44 1292 675207; fax +44 1292 675704; e-mail RApublications@baesystems.com; Internet <http://www.baesystems.com/Businesses/RegionalAircraft/index.htm>.

(4) You may review copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may also review copies of the service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on September 23, 2010.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2010-25018 Filed 10-6-10; 8:45 am]

BILLING CODE 4910-13-P

**DEPARTMENT OF TRANSPORTATION
 Federal Aviation Administration
 14 CFR Part 39**

[Docket No. FAA-2010-0950; Directorate Identifier 2009-NM-194-AD; Amendment 39-16460; AD 2009-19-06]

RIN 2120-AA64

Airworthiness Directives; Boeing Model 747-100, 747-100B, 747-100B SUD, 747-200B, 747-200F, 747-300, 747-400, 747-400D, 747SP, and 747SR Series Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule; request for comments.

SUMMARY: This document publishes in the **Federal Register** an amendment adopting airworthiness directive (AD) 2009-19-06 that was sent previously by individual notices to the known U.S. owners and operators of affected airplanes identified above. This AD requires installing certain equipment on the flight deck door. This AD was prompted by reports that the current design of the flight deck door is defective. We are issuing this AD to prevent failure of this equipment, which could jeopardize flight safety.

DATES: This AD becomes effective October 12, 2010 to all persons except those persons to whom it was made immediately effective by AD 2009-19-06, which contained the requirements of this amendment.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in the AD as of October 12, 2010.

We must receive comments on this AD by November 22, 2010.

ADDRESSES: You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* 202-493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.
- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, Washington 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; e-mail

me.boecom@boeing.com; Internet <https://www.myboeingfleet.com>.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT:

Robert Kaufman, Aerospace Engineer, Cabin Safety and Environmental Systems Branch, ANM-150S, FAA, Seattle ACO, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 917-6433; fax (425) 917-6590.

SUPPLEMENTARY INFORMATION: On September 9, 2009, we issued AD 2009-19-06, which applies to certain Boeing Model 747-100, 747-100B, 747-100B SUD, 747-200B, 747-200F, 747-300, 747-400, 747-400D, 747SP, and 747SR series airplanes.

Background

We have received a report indicating that the current design of the flight deck door is defective. This condition, if not corrected, could jeopardize flight safety.

Relevant Service Information

We reviewed Boeing Service Bulletin 747-52-2293, dated September 4, 2009. The service bulletin describes procedures for installing certain equipment associated with the flight deck door.

FAA's Determination and Requirements of This AD

Since the unsafe condition described is likely to exist or develop on other airplanes of the same type design, we issued AD 2009-19-06 to prevent failure of the flight deck door, which could jeopardize flight safety. The AD requires accomplishing the actions specified in the service information previously described.

We have determined that notice and opportunity for prior public comment on AD 2009-19-06 were contrary to the public interest, and good cause existed to make the AD effective immediately by individual notices issued on September 9, 2009, to the known U.S. owners and operators of certain Boeing Model 747-100, 747-100B, 747-100B SUD, 747-200B, 747-200F, 747-300,

747-400, 747-400D, 747SP, and 747SR series airplanes. These conditions still exist, and the AD is hereby published in the **Federal Register** as an amendment to section 39.13 of the Federal Aviation Regulations (14 CFR 39.13) to make it effective to all persons.

Comments Invited

This AD is a final rule that involves requirements affecting flight safety, and we did not provide you with notice and an opportunity to provide your comments before it becomes effective. However, we invite you to send any written data, views, or arguments about this AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2010-0950; Directorate Identifier 2009-NM-194-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this AD. We will consider all comments received by the closing date and may amend this AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this AD.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in subtitle VII, part A, subpart III, section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and

responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979), and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

You can find our regulatory evaluation and the estimated costs of compliance in the AD Docket.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

■ Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

2009-19-06 The Boeing Company:

Amendment 39-16460. Docket No. FAA-2010-0950; Directorate Identifier 2009-NM-194-AD.

Effective Date

(a) This AD becomes effective October 12, 2010, to all persons except those persons to whom it was made immediately effective by AD 2009-19-06, issued on September 9, 2009, which contained the requirements of this amendment.

Affected ADs

(b) None.

Applicability

(c) This AD applies to Boeing Model 747-100, 747-100B, 747-100B SUD, 747-200B, 747-200F, 747-300, 747-400, 747-400D, 747SP, and 747SR series airplanes, certificated in any category; as identified in Boeing Service Bulletin 747-52-2293, dated September 4, 2009.

Subject

(d) Air Transport Association (ATA) of America Code 52: Doors.

Unsafe Condition

(e) This AD was prompted by reports that the current design of the flight deck door is

defective. We are issuing this AD to prevent failure of this equipment, which could jeopardize flight safety.

Compliance

(f) Comply with this AD within the compliance times specified, unless already done.

Door Equipment Installation

(g) Within 30 days after the effective date of this AD, install certain equipment associated with the flight deck door, in accordance with Boeing Service Bulletin 747-52-2293, dated September 4, 2009.

Alternative Methods of Compliance (AMOCs)

(h)(1) The Manager, Seattle Aircraft Certification Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to Robert Kaufman, Aerospace Engineer, Cabin Safety and Environmental Systems Branch, ANM-150S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 917-6433; fax (425) 917-6590. Or e-mail information to 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your principal maintenance inspector (PMI) or principal avionics inspector (PAI), as appropriate, or lacking a principal inspector, your local Flight Standards District Office. The AMOC approval letter must specifically refer to this AD.

Incorporation by Reference

(i) You must use Boeing Service Bulletin 747-52-2293, dated September 4, 2009, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, Washington 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; e-mail me.boecom@boeing.com; Internet <https://www.myboeingfleet.com>.

(3) You may review copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221.

(4) You may also review copies of the service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on September 23, 2010.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2010-25194 Filed 10-6-10; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2010-0643; Directorate Identifier 2010-NM-030-AD; Amendment 39-16462; AD 2010-21-02]

RIN 2120-AA64

Airworthiness Directives; Bombardier, Inc. Model DHC-8 Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for the products listed above. This AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

The landing gear alternate extension system in the cockpit is accessible through an access panel located on the cockpit floor. There have been reports of failure of the access panel latch assembly as a consequence of repeated closure of the access panel involving the use of excessive force. Failure of the latch assembly can result in the access panel being jammed in the closed position, and require mechanical prying to open.

An undetected or uncorrected latch failure condition in the access panel can prevent immediate access to the landing gear alternate extension system by the flight crew during an emergency. * * *

We are issuing this AD to require actions to correct the unsafe condition on these products.

DATES: This AD becomes effective November 12, 2010.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of November 12, 2010.

ADDRESSES: You may examine the AD docket on the Internet at <http://www.regulations.gov> or in person at the U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC.

FOR FURTHER INFORMATION CONTACT:

Craig Yates, Aerospace Engineer, Airframe and Mechanical Systems Branch, ANE-171, New York Aircraft Certification Office, FAA, 1600 Stewart Avenue, Suite 410, Westbury, New York 11590; telephone (516) 228-7355; fax (516) 794-5531.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that would apply to the specified products. That NPRM was published in the **Federal Register** on July 1, 2010 (75 FR 38064). That NPRM proposed to correct an unsafe condition for the specified products. The MCAI states:

The landing gear alternate extension system in the cockpit is accessible through an access panel located on the cockpit floor. There have been reports of failure of the access panel latch assembly as a consequence of repeated closure of the access panel involving the use of excessive force. Failure of the latch assembly can result in the access panel being jammed in the closed position, and require mechanical prying to open.

An undetected or uncorrected latch failure condition in the access panel can prevent immediate access to the landing gear alternate extension system by the flight crew during an emergency. This Directive requires the replacement of the existing latch assembly with a stronger modified latch assembly.

You may obtain further information by examining the MCAI in the AD docket.

Relevant Service Information

Bombardier, Inc. issued Service Bulletin 8-32-166, Revision B, dated March 2, 2010. We cited Bombardier Service Bulletin 8-32-166, Revision A, dated January 29, 2009, in the NPRM. Bombardier Service Bulletin 8-32-166, Revision B, dated March 2, 2010, updates the References section and adds a Note to the Accomplishment Instructions section. We have changed paragraph (g) of this AD to specify Revision B of that service bulletin, and added Bombardier Service Bulletin 8-32-166, Revision A, dated January 29, 2009, to paragraph (h) of this AD.

Comments

We gave the public the opportunity to participate in developing this AD. We considered the comments received. Air Line Pilots Association, International, supports the NPRM. Hawaii Island Air, Piedmont Airlines, and Mesa Airlines request that we revise the NPRM to refer to Bombardier Service Bulletin 8-32-166, Revision B, dated March 2, 2010, as described previously.