

liability on its guaranty, is being modified because, in addition to the grounds stated in this regulation, the lender's failure to comply with its policies and procedures governing floor plan financing or the terms and procedures set forth in this **Federal Register** notice or the DFP Procedural Guide may result in denial of SBA's guaranty on the loan, in full or in part. In addition, if the proceeds of the DFP line of credit are used to replace a same institution floor plan line and the borrower defaults on the DFP line of credit within 90 days of initial disbursement, SBA may deny liability on its guaranty of the DFP line. The regulation at 13 CFR 120.520(a) is also being waived to allow lenders to make demand on SBA to honor its guaranty in the above situations without being required to liquidate all business personal property securing the line of credit first.

The statutory language creating this DFP Pilot overrides the regulatory prohibition against floor plan financing or other revolving line credit (except under 120.390) found in 13 CFR 120.130(c).

All other provisions of the Small Business Act applicable to the 7(a) loan program apply to loans made under the DFP Pilot. Unless waived or modified by this Notice, all the regulations applicable to the 7(a) loan program apply to loans made under the DFP Pilot. All standard operating procedures applicable to the 7(a) loan program that are not superseded by any provision of this Notice or the DFP Procedural Guide apply to loans made under this pilot.

Lenders must use prudent lending practices in the making, servicing and liquidating of SBA-guaranteed floor plan lines of credit and must comply with all SBA Loan Program Requirements that are not superseded by any provisions of this Notice or the DFP Procedural Guide.

SBA will provide more detailed guidance in the form of a procedural guide which will be available on SBA's Web site, <http://www.sba.gov>. SBA may also provide additional guidance, if needed, through SBA notices, which will also be published on SBA's Web site, <http://www.sba.gov>.

Questions on the DFP Pilot may be directed to the Lender Relations Specialist in the local SBA district office. The local SBA district office may be found at <http://www.sba.gov/localresources/index.html>.

Authority: 15 U.S.C. 636(a)(34) and 13 CFR 120.3.

Dated: February 3, 2011.

Karen G. Mills,

Administrator.

[FR Doc. 2011-2836 Filed 2-8-11; 8:45 am]

BILLING CODE 8025-01-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2009-0113; Directorate Identifier 2008-NE-25-AD; Amendment 39-16602; AD 2011-04-02]

RIN 2120-AA64

Airworthiness Directives; Hamilton Sundstrand Propellers Model 247F Propellers

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for the products listed above. This AD requires removing affected propeller blades from service. This AD was prompted by reports of blades with corrosion pits in the tulip area of the blades. We are issuing this AD to prevent cracks from developing in the tulip area of the blade, which could result in separation of the blade and possible loss of airplane control.

DATES: This AD is effective March 16, 2011.

ADDRESSES:

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The address for the Docket Office (phone: 800-647-5527) is Document Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT:

Michael Schwetz, Aerospace Engineer, Boston Aircraft Certification Office, FAA, Engine and Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803; telephone (781) 238-7761; fax (781) 238-7170; e-mail: michael.schwetz@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a supplemental notice of proposed rulemaking (SNPRM) to amend 14 CFR part 39 to include an AD that would apply to the specified products. That SNPRM published in the **Federal Register** on October 8, 2010 (75 FR 62333). That SNPRM proposed to require removing affected propeller blades from service.

Comments

We gave the public the opportunity to participate in developing this AD. We received no comments on the SNPRM or on the determination of the cost to the public.

Conclusion

We reviewed the relevant data and determined that air safety and the public interest require adopting the AD as proposed except for minor changes to the compliance date for certain serial number (S/N) propeller blades. The SNPRM proposed to require removing propeller blades part number (P/N) 817370-1, S/Ns FR2449 to FR2958 inclusive, FR20010710 to FR20010722 inclusive, and FR20010723RT to FR20020127RT inclusive, before December 31, 2010. We determined that those S/N propeller blades should be removed within the same compliance time as propeller blades P/N 817370-1, S/Ns FR2018, FR2103, FR2108, FR2109, FR2111, FR2123, FR2183, FR2187, FR2262, FR2276 through FR2279 inclusive, and FR2398. We have determined that these minor changes:

- Are consistent with the intent that was proposed in the SNPRM for correcting the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the SNPRM.

Costs of Compliance

We estimate that this AD will affect 10 propellers installed on airplanes of U.S. registry. We also estimate that it will take about 16 work-hours per propeller to perform the required actions, and that the average labor rate is \$85 per work-hour. Required parts will cost about \$50 per propeller. Based on these figures, we estimate the total cost of this AD to U.S. operators to be \$14,100.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in subtitle VII, part A, subpart III, section 44701: "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

2011-04-02 Hamilton Sundstrand

Corporation: Amendment 39-16602;
Docket No. FAA-2009-0113; Directorate Identifier 2008-NE-25-AD.

Effective Date

- (a) This AD is effective March 16, 2011.

Affected ADs

- (b) None.

Applicability

(c) This AD applies to Hamilton Sundstrand model 247F series propellers with blades part number (P/N) 817370-1, serial numbers (S/Ns) FR2018, FR2103, FR2108, FR2109, FR2111, FR2123, FR2183, FR2187, FR2262, FR2276 through FR2279 inclusive, FR 2398, FR2449 to FR2958 inclusive, FR20010710 to FR20010722 inclusive, and FR20010723RT to FR20020127RT inclusive, installed. These propellers are installed on, but not limited to, ATR-GIE Avions de Transport Regional ATR72-210 and ATR72-210E airplanes.

Unsafe Condition

(d) This AD results from reports of blades with corrosion pits in the tulip area of the blades. We are issuing this AD to prevent cracks from developing in the tulip area of the blade, which could result in separation of the blade and possible loss of airplane control.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified unless the actions have already been done.

Removing Blades P/N 817370-1

(f) Remove from service, blades P/N 817370-1, S/Ns FR2018, FR2103, FR2108, FR2109, FR2111, FR2123, FR2183, FR2187, FR2262, FR2276 through FR2279, FR2398, FR2449 to FR2958 inclusive, FR20010710 to FR20010722 inclusive, and FR20010723RT to FR20020127RT inclusive, within 30 days after the effective date of this AD.

Alternative Methods of Compliance

(g) The Manager, Boston Aircraft Certification Office, has the authority to approve alternative methods of compliance for this AD if requested using the procedures found in 14 CFR 39.19.

Related Information

(h) For more information about this AD, contact Michael Schwetz, Aerospace Engineer, Boston Aircraft Certification Office, FAA, Engine and Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803; telephone (781) 238-7761; fax (781) 238-7170; e-mail: michael.schwetz@faa.gov.

Issued in Burlington, Massachusetts, on January 31, 2011.

Peter A. White,

Acting Manager, Engine & Propeller Directorate, Aircraft Certification Service.

[FR Doc. 2011-2758 Filed 2-8-11; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF COMMERCE

Bureau of Industry and Security

15 CFR Part 748

[Docket No. 100826397-1059-02]

RIN 0694-AE98

Simplified Network Application Processing System, On-line Registration and Account Maintenance

AGENCY: Bureau of Industry and Security, Commerce.

ACTION: Final rule.

SUMMARY: The Bureau of Industry and Security (BIS) amends the Export Administration Regulations to implement a mandatory on-line registration process for obtaining an account to submit license applications and similar documents electronically through SNAP-R. This final rule sets forth the information that parties registering on-line are required to provide to BIS and the duties that registered parties have with respect to keeping information in their accounts current. This rulemaking is consistent with the goals and principles of Executive Orders 13563 and 12866, which are to enhance effectiveness and efficiency and to promote transparency and openness in government, and the Presidential Memorandum on Regulatory Flexibility, Small Business, and Job Creation (January 18, 2011).

DATES: *Effective date:* March 11, 2011.

Compliance dates: Beginning on April 11, 2011, all new SNAP-R registrations must be made in accordance with this rule.

Beginning on June 10, 2011 accounts of filing entities that do not have account administrators will not be accessible until an existing individual user for that entity logs-on to SNAP-R and registers as account administrator.

Beginning on September 8, 2011 the accounts of filing entities that do not have an account administrator will become inactive. In order to reactivate the account, filing entities will have to complete the entire registration process that applies to new entities.

FOR FURTHER INFORMATION CONTACT:

Thomas W. Andrukonis, Director, Export Management and Compliance Division, Office of Exporter Services, telephone (202) 482-6393, e-mail tandruko@bis.doc.gov.

SUPPLEMENTARY INFORMATION:

Immediate Voluntary Implementation of On-Line Registration

Beginning on February 9, 2011, BIS will accept on-line SNAP-R