

Alternative Methods of Compliance (AMOCs)

(h)(1) The Manager, International Branch, ANM-116, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Tim Dulin, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601

Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-2141; fax (425) 227-1149.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your principal maintenance inspector (PMI) or principal avionics inspector (PAI),

as appropriate, or lacking a principal inspector, your local Flight Standards District Office. The AMOC approval letter must specifically refer to this AD.

Material Incorporated by Reference

(i) You must use the service information contained in Table 2 of this AD, as applicable, to do the actions required by this AD, unless the AD specifies otherwise.

TABLE 2—MATERIAL INCORPORATED BY REFERENCE

Airbus Service Bulletin—	Dated—
A300-25-0486, including Appendix	September 21, 2009.
A300-25-6218, including Appendix	September 21, 2009.
A310-25-2206, including Appendix	September 21, 2009.
A320-25-1666, including Appendix	September 21, 2009.
A330-25-3424, including Appendix	September 21, 2009.
A340-25-4326, including Appendix	September 21, 2009.
A340-25-5169, including Appendix	September 18, 2009.
A380-25-8058, including Appendix	September 21, 2009.

(1) The Director of the Federal Register approved the incorporation by reference of the service information contained in Table 2 of this AD under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) Use the contact information specified in paragraphs (i)(2)(i), (i)(2)(ii), (i)(2)(iii), and (i)(2)(iv), as applicable, for service information identified in this AD.

(i) For Model A300, A300-600, and A310 series airplanes, contact Airbus SAS—EAW (Airworthiness Office), 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; e-mail account.airworth-eas@airbus.com; Internet <http://www.airbus.com>.

(ii) For Model A318, A319, A320, and A321 series airplanes, contact Airbus, Airworthiness Office—EAS, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; e-mail account.airworth-eas@airbus.com; Internet <http://www.airbus.com>.

(iii) For Model A330-300, A340-200, A340-300, A340-500, A340-600 series airplanes, and Model A330-201, A330-202, A330-203, A330-223, A330-243 airplanes, contact Airbus SAS—Airworthiness Office—EAL, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 45 80; e-mail airworthiness.A330-A340@airbus.com; Internet <http://www.airbus.com>.

(iv) For Model A380-800 series airplanes, contact Airbus SAS—EANA (Airworthiness Office), 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 562 110 253; Fax +33 562 110 307; e-mail account.airworth-A380@airbus.com; Internet <http://www.airbus.com>.

(3) You may review copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221.

(4) You may also review copies of the service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this

material at an NARA facility, call 202-741-6030, or go to http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on December 14, 2010.

Michael Kaszycki,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2010-33318 Filed 1-7-11; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2010-1297; Directorate Identifier 2010-CE-068-AD; Amendment 39-16569; AD 2010-26-54]

RIN 2120-AA64

Airworthiness Directives; Cessna Aircraft Company (Cessna) (Type Certificate A00003SE Previously Held by Columbia Aircraft Manufacturing (Previously The Lancair Company)) Models LC41-550FG and LC42-550FG Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; request for comments.

SUMMARY: We are adopting a new airworthiness directive (AD) for the products listed above. This emergency AD was sent previously to all known U.S. owners and operators of these airplanes. This AD requires obtaining written approval from the Manager, Wichita Aircraft Certification Office (ACO), to operate the airplane. This written approval must clearly state that

operation is approved per Emergency AD 2010-26-54. This AD was prompted by a Cessna Model LC41-550FG airplane that suffered a significant structural failure in the wing during a production acceptance flight test. We are issuing this AD to prevent catastrophic failure of the wing due to disbonding of the wing skin from the wing spar.

DATES: This AD is effective January 10, 2011 to all persons except those persons to whom it was made immediately effective by Emergency AD 2010-26-54, issued on December 17, 2010, which contained the requirements of this amendment.

We must receive comments on this AD by February 24, 2011.

ADDRESSES: You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Operations Office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The street address for

the Docket Operations Office (phone: 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Gary Park, Aerospace Engineer, Wichita ACO, FAA, 1801 Airport Road, Wichita, KS 67209; phone: (316) 946-4123; fax: (316) 946-4107; e-mail: gary.park@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

On December 10, 2010, we issued Emergency AD 2010-26-53, which requires obtaining written approval from the Manager, Wichita ACO, to operate the airplane. The written approval must clearly state that operation is approved per Emergency AD 2010-26-53. This action was prompted by a Cessna Model LC41-550FG airplane that suffered a significant structural failure in the wing during a production acceptance flight test. The wing skin disbonded from the upper forward wing spar. The length of the disbond was approximately 7 feet.

Since issuing AD 2010-26-53, we determined the need to increase the serial numbers in the Applicability section and to correct a serial number in the Applicability section. We issued Emergency AD 2010-26-54, dated December 17, 2010, which retains the actions of the previous AD, adds serial numbers to the Applicability section, and corrects a serial number in the Applicability section.

This condition, if not corrected, could result in catastrophic failure of the wing due to disbonding of the wing skin from the wing spar.

FAA's Determination

We are issuing this AD because we evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop in other products of the same type design.

AD Requirements

This AD requires obtaining written approval from the Manager, Wichita ACO, to operate the airplane. The written approval must clearly state that operation is approved per Emergency AD 2010-26-54.

Interim Action

We consider this AD interim action.

FAA's Determination of the Effective Date

An unsafe condition exists that requires the immediate adoption of this AD. The FAA has found that the risk to the flying public justifies waiving notice and comment prior to adoption of this

rule because disbonding of the wing skin from the wing spar could result in catastrophic failure of the wing. Therefore, we find that notice and opportunity for prior public comment are impracticable and that good cause exists for making this amendment effective in less than 30 days.

Comments Invited

This AD is a final rule that involves requirements affecting flight safety and was not preceded by notice and an opportunity for public comment. However, we invite you to send any written data, views, or arguments about this AD. Send your comments to an address listed under the **ADDRESSES** section. Include the docket number FAA-2010-1297 and Directorate Identifier 2010-CE-068-AD at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this AD. We will consider all comments received by the closing date and may amend this AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this AD.

Costs of Compliance

We estimate that this AD affects 13 airplanes of U.S. registry.

There are no labor or parts costs associated with this AD action.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in subtitle VII, part A, subpart III, section 44701: "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

2010-26-54 Cessna Aircraft Company (Type Certificate A00003SE previously held by Columbia Aircraft Manufacturing (previously The Lancair Company)): Amendment 39-16569; Docket No. FAA-2010-1297; Directorate Identifier 2010-CE-068-AD.

Effective Date

(a) This AD is effective January 10, 2011 to all persons except those persons to whom it was made immediately effective by Emergency AD 2010-26-54, issued on December 17, 2010, which contained the requirements of this amendment.

Affected ADs

(b) None.

Applicability

(c) This AD applies to the following Cessna Aircraft Company (Cessna) (Type Certificate A00003SE previously held by Columbia Aircraft Manufacturing (previously The Lancair Company)) airplanes certified in any category, as identified in table 1 of this AD:

TABLE 1—APPLICABILITY

Model	Serial Nos.
LC41-550FG	41028, 41705, 411114, 411160, 411161, 411162, 411163, 411164, 411165, 411167, 411170, and 411171.
LC42-550FG	42517.

Subject

(d) Joint Aircraft System Component (JASC)/Air Transport Association (ATA) of America Code 57, Wings.

Unsafe Condition

(e) This AD was prompted by a Cessna Model LC41-550FG airplane that suffered a significant structural failure in the wing during a production acceptance flight test. The wing skin disbonded from the upper forward wing spar. The length of the disbond was approximately 7 feet. We are issuing this AD to prevent catastrophic failure of the wing due to disbonding of the wing skin from the wing spar.

Compliance

(f) Comply with this AD within the compliance times specified, unless already done.

Operation Restriction

(g) As of the effective date of this AD, do not operate the airplane without written approval from the Manager, Wichita Aircraft Certification Office (ACO). This written approval must clearly state that operation is approved per AD 2010-26-54.

Special Flight Permit

(h) A special flight permit requires written approval from the Manager, Wichita ACO. This written approval must clearly state that operation is approved per AD 2010-26-54.

Alternative Methods of Compliance (AMOCs)

(i)(1) The Manager, Wichita ACO, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in the Related Information section of this AD.

(2) Before using any approved AMOC, notify your Principal Maintenance Inspector or Principal Avionics Inspector, as appropriate, or lacking a principal inspector, your local Flight Standards District Office.

Related Information

(j) For further information about this AD, contact: Gary Park, Aerospace Engineer, Wichita ACO, FAA, 1801 Airport Road, Wichita, KS 67209; phone: (316) 946-4123; fax: (316) 946-4107; e-mail: gary.park@faa.gov.

Issued in Kansas City, Missouri, on December 27, 2010.

Earl Lawrence,

Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2010-33336 Filed 1-7-11; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2010-1280; Directorate Identifier 2010-NM-270-AD; Amendment 39-16572; AD 2011-01-15]

RIN 2120-AA64

Airworthiness Directives; The Boeing Company Model 757-200, -200CB, and -300 Series Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; request for comments.

SUMMARY: We are adopting a new airworthiness directive (AD) for the products listed above. This AD requires repetitive inspections for cracking of the fuselage skin of the crown skin panel along the chem-milled step at stringers S-4 left and S-4 right, from stations (STA) 297 through 439, and repair if necessary. This AD also includes terminating action for the repetitive inspections of the repaired areas only. This AD was prompted by reports of cracking in the fuselage skin of the crown skin panel. We are issuing this AD to detect and correct fatigue cracking of the fuselage skin of the crown skin panel, which could result in pressure venting and consequent rapid decompression of the airplane.

DATES: This AD is effective January 25, 2011.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in the AD as of January 25, 2011.

We must receive comments on this AD by February 24, 2011.

ADDRESSES: You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* 202-493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.
- *Hand Delivery:* U.S. Department of Transportation, Docket Operations,

M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, Washington 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; e-mail me.boecom@boeing.com; Internet <https://www.myboeingfleet.com>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (phone: 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Nancy Marsh, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 917-6440; fax (425) 917-6590; e-mail: nancy.marsh@faa.gov.

SUPPLEMENTARY INFORMATION:**Discussion**

We have received reports of cracking in the fuselage skin of the crown skin panel. On one airplane, the crack was 10.75 inches long, midway between stations (STA) 420 and 439, just above the lap joint at stringer 4L (left) of the chem-milled step. The airplane had accumulated 24,631 total flight cycles. On another airplane, there was an opening from a crack in the fuselage above and aft of the passenger entry doorway. One edge of the opening ran approximately 18 inches in the forward-to-aft direction; the other edge ran approximately 12 inches along the chem-milled pocket edge above stringer 4L. Additionally, a 1.3-inch crack was found in the skin forward of the opening in the adjacent skin bay also in the chem-milled step above stringer 4L. The airplane had accumulated 22,450 total