

Rules and Regulations

Federal Register

Vol. 73, No. 147

Wednesday, July 30, 2008

This section of the FEDERAL REGISTER contains regulatory documents having general applicability and legal effect, most of which are keyed to and codified in the Code of Federal Regulations, which is published under 50 titles pursuant to 44 U.S.C. 1510.

The Code of Federal Regulations is sold by the Superintendent of Documents. Prices of new books are listed in the first FEDERAL REGISTER issue of each week.

FARM CREDIT ADMINISTRATION

12 CFR Part 652

RIN 3052-AC36

Federal Agricultural Mortgage Corporation Funding and Fiscal Affairs; Risk-Based Capital Requirements; Effective Date

AGENCY: Farm Credit Administration.

ACTION: Notice of effective date.

SUMMARY: The Farm Credit Administration (FCA or Agency), through the FCA Board (Board), issued a final rule under part 652 on June 5, 2008 (73 FR 31937) amending our capital regulations governing the Federal Agricultural Mortgage Corporation. In accordance with 12 U.S.C. 2252, the effective date of the final rule is 30 days from the date of publication in the **Federal Register** during which either or both Houses of Congress are in session. Based on the records of the sessions of Congress, the effective date of the regulations is July 25, 2008.

DATES: *Effective Date:* The regulation amending 12 CFR part 652 published on June 5, 2008 (73 FR 31937) is effective July 25, 2008.

FOR FURTHER INFORMATION CONTACT:

Joseph T. Connor, Associate Director for Policy and Analysis, Office of Secondary Market Oversight, Farm Credit Administration, McLean, Virginia 22102-5090, (703) 883-4280, TTY (703) 883-4434, or

Rebecca S. Orlich, Senior Counsel, Office of General Counsel, Farm Credit Administration, McLean, Virginia 22102-5090, (703) 883-4420, TTY (703) 883-4020.

(12 U.S.C. 2252(a)(9) and (10))

Dated: July 25, 2008.

Roland E. Smith,

Secretary, Farm Credit Administration Board.

[FR Doc. E8-17462 Filed 7-29-08; 8:45 am]

BILLING CODE 6705-01-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2008-0042; Directorate Identifier 2007-SW-26-AD; Amendment 39-15614; AD 2008-15-02]

RIN 2120-AA64

Airworthiness Directives; Eurocopter Deutschland GmbH Model MBB-BK 117C-2 Helicopters

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for Eurocopter Deutschland GmbH (Eurocopter) Model MBB-BK 117C-2 helicopters. This AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The European Aviation Safety Agency for the Republic of Germany, with which we have a bilateral agreement, states in the MCAI:

During inadvertent operation of the fire extinguishing system, in one case it occurred that one of the two injection tubes became disconnected. This condition, if not corrected, could affect the ability of the fire extinguishing system to perform its intended function in the case of activation.

The inability of the fire extinguishing system to suppress an engine fire creates an unsafe condition. We are issuing this AD to correct the unsafe condition by further securing the injection tubes with improved clamps, allowing suppression of a contained engine fire, and subsequent loss of the helicopter.

DATES: This AD becomes effective on September 3, 2008.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of September 3, 2008.

ADDRESSES: You may examine the AD docket on the Internet at <http://www.regulations.gov> or in Room W12-140 on the ground floor of the West Building, 1200 New Jersey Avenue SE., Washington, DC 20590.

www.regulations.gov or in Room W12-140 on the ground floor of the West Building, 1200 New Jersey Avenue SE., Washington, DC 20590.

You can get the service information identified in this AD from American Eurocopter Corporation, 2701 Forum Drive, Grand Prairie, Texas 75053-4005, telephone (972) 641-3460, fax (972) 641-3527.

FOR FURTHER INFORMATION CONTACT: John Strasburger, Aviation Safety Engineer, FAA, Rotorcraft Directorate, Regulations and Guidance Group, Fort Worth, Texas 76193-0111, telephone (817) 222-5167, fax (817) 222-5961.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that would apply to the specified products. That NPRM was published in the **Federal Register** on January 23, 2008 (73 FR 3885). That NPRM proposed to correct an unsafe condition for the specified products. The MCAI states:

During inadvertent operation of the fire extinguishing system, in one case it occurred that one of the two injection tubes became disconnected. This condition, if not corrected, could affect the ability of the fire extinguishing system to perform its intended function in the case of activation.

The inability of the fire extinguishing system to suppress an engine fire creates an unsafe condition. The proposed actions are intended to address this unsafe condition by further securing the injection tubes with improved clamps, allowing suppression of a contained engine fire, and preventing an uncontained engine fire and subsequent loss of the helicopter.

Comments

We gave the public the opportunity to participate in developing this AD. We received no comments on the NPRM or on the determination of the cost to the public.

Conclusion

We reviewed the available data and determined that air safety and the public interest require adopting the AD as proposed.

Differences Between This AD and the MCAI or Service Information

We have reviewed the MCAI and related service information and, in