

the tolerances of these gaskets. Since an unsafe condition has been identified that is likely to exist or develop on aircraft of these type designs, this Airworthiness Directive requires inspection [to verify if the J1/P1 and J2/P2 interface connectors can be properly locked and gaskets are present] and, when necessary, replacement of the affected PSU Panel 11 and 12 Interface Connector gaskets. Corrective actions include installing a gasket, verifying that the J1 and J2 receptacle locking tabs are not deformed, replacing the receptacle, and installing a new PSU panel.

Actions and Compliance

(f) Within 36 months after the effective date of this AD unless already done, do the following actions.

(1) Inspect the affected Honeywell International (Grimes Aerospace) PSU Panel Interface Connectors for proper locking of the connectors and to verify that gaskets are installed, in accordance with Part 3. Accomplishment Instructions of Fokker Service Bulletin SBF50-25-061 or SBF100-25-108, both dated March 31, 2006, as applicable.

(2) When discrepancies are found, before next flight, do all applicable corrective actions as detailed in Part 3. Accomplishment Instructions of Fokker Service Bulletin SBF50-25-061 or SBF100-25-108, both dated March 31, 2006, as applicable.

FAA AD Differences

Note: This AD differs from the MCAI and/or service information as follows: No differences.

Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Branch, ANM-116, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Tom Rodriguez, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-1137; fax (425) 227-1149. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements:* For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act, the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Related Information

(h) Refer to MCAI CAA-NL, Dutch Airworthiness Directive NL-2006-008, dated July 14, 2006, and Fokker Service Bulletin SBF50-25-061 or SBF100-25-108, both dated March 31, 2006, for related information.

Issued in Renton, Washington, on December 21, 2007.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E8-252 Filed 1-9-08; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF THE TREASURY

Internal Revenue Service

26 CFR Part 1

[REG-118886-06]

RIN 1545-BF65

Clarification to Section 6411 Regulations; Hearing

AGENCY: Internal Revenue Service (IRS), Treasury.

ACTION: Notice of public hearing on proposed rulemaking.

SUMMARY: This document provides notice of a public hearing on a notice of proposed rulemaking under section 6411 of the Internal Revenue Code relating to the computation and allowance of the tentative carryback adjustment. These regulations clarify that for purposes of allowing the tentative adjustment, the IRS may credit or reduce the tentative adjustment by an assessed tax liability, whether or not that tax liability was assessed before the date the application for tentative carryback is filed, and other unassessed liabilities in certain other circumstances.

DATES: The public hearing is being held on Tuesday, February 5, 2008, at 10 a.m. The IRS must receive outlines of the topics to be discussed at the hearing by Tuesday, January 22, 2008.

ADDRESSES: The public hearing is being held in the room 2140, Internal Revenue Building, 1111 Constitution Avenue, NW., Washington, DC. Send submissions to: CC: PA: LPD: PR (REG-118886-06), room 5203, Internal Revenue Service, P.O. Box 7604, Ben Franklin Station, Washington, DC 20044. Submissions may be hand-delivered Monday through Friday between the hours of 8 a.m. and 4 p.m. to CC: PA: LPD: PR (REG-118886-06), Courier's Desk, Internal Revenue Service, 1111 Constitution Avenue,

NW., Washington, DC. Alternatively, taxpayers may submit electronic outlines of oral comments via the Federal eRulemaking Portal at <http://www.regulations.gov>.

FOR FURTHER INFORMATION CONTACT:

Concerning the proposed regulations, Cynthia McGreevy, (202) 622-4910; concerning submissions of comments, the hearing, and/or to be placed on the building access list to attend the hearing, Richard A. Hurst at Richard.A.Hurst@irs.counsel.treas.gov or (202) 622-7180 (not toll-free numbers).

SUPPLEMENTARY INFORMATION: The subject of the public hearing is the notice of proposed rulemaking (REG-118886-06) that was published in the **Federal Register** on Monday, August 27, 2007 (72 FR 48952).

Persons who wish to present oral comments at the hearing that submitted written comments by November 26, 2007, must submit an outline of the topics to be discussed and the amount of time to be devoted to each topic (signed original and eight (8) copies) by January 22, 2008.

A period of 10 minutes is allotted to each person for presenting oral comments. After the deadline for receiving outlines has passed, the IRS will prepare an agenda containing the schedule of speakers. Copies of the agenda will be made available, free of charge, at the hearing or in the Freedom of Information Reading Room (FOIA RR) (Room 1621) which is located at the 11th and Pennsylvania Avenue, NW., entrance, 1111 Constitution Avenue, NW., Washington, DC.

Because of access restrictions, the IRS will not admit visitors beyond the immediate entrance area more than 30 minutes before the hearing starts. For information about having your name placed on the building access list to attend the hearing, see the **FOR FURTHER INFORMATION CONTACT** section of this document.

Cynthia Grigsby,

Acting Chief, Publications and Regulations Branch, Legal Processing Division, Associate Chief Counsel (Procedure and Administration).

[FR Doc. E8-220 Filed 1-9-08; 8:45 am]

BILLING CODE 4830-01-P