Dated: August 4, 2010. B.A. Compagnoni, Captain, U.S. Coast Guard, Captain of the Port Honolulu. [FR Doc. 2010–20364 Filed 8–17–10; 8:45 am] BILLING CODE 9110–04–P

DEPARTMENT OF HOMELAND SECURITY

Federal Emergency Management Agency

44 CFR Part 67

[Docket ID FEMA-2008-0020; Internal Agency Docket No. FEMA-B-1066]

Proposed Flood Elevation Determinations

AGENCY: Federal Emergency Management Agency, DHS. **ACTION:** Proposed rule; correction.

SUMMARY: On September 8, 2009, FEMA published in the Federal Register a proposed rule that contained an erroneous table. This notice provides corrections to that table, to be used in lieu of the information published at 74 FR 46047. The table provided here represents the flooding sources, location of referenced elevations, effective and modified elevations, and communities affected for York County, Maine (All Jurisdictions). Specifically, it addresses the following flooding sources: Atlantic Ocean, Bonny Eagle Pond, Cape Porpoise Harbor, Cleaves Cove, Coffin Brook, Coffin Brook Tributary 1, Driscoll Brook, Ferguson Brook, Goosefare Brook, Great East Lake, Jones Brook (backwater effects from Scarborough River), Keay Brook, Kennebunk River, Little Ossipee River, Little River, Little River (backwater effects from Scarborough River), Mill Brook (backwater effects from Scarborough River), Mousam River,

Mulloy Brook, Piscataqua River, Portsmouth Harbor, Province Lake, Saco River, Salmon Falls River, Sampson Cove, Spruce Creek, Stump Pond, The Pool, Worster Brook, and Worster Brook Tributary 3.

DATES: Comments are to be submitted on or before November 16, 2010. ADDRESSES: You may submit comments, identified by Docket No. FEMA–B– 1066, to Roy E. Wright, Deputy Director, Risk Analysis Division, Federal Insurance and Mitigation Administration, Federal Emergency Management Agency, 500 C Street, SW., Washington, DC 20472, (202) 646–3461 or (e-mail) *roy.e.wright@dhs.gov.*

FOR FURTHER INFORMATION CONTACT: Roy E. Wright, Deputy Director, Risk Analysis Division, Federal Insurance and Mitigation Administration, Federal Emergency Management Agency, 500 C Street, SW., Washington, DC 20472, (202) 646–3461 or (e-mail) roy.e.wright@dhs.gov.

SUPPLEMENTARY INFORMATION: The Federal Emergency Management Agency (FEMA) publishes proposed determinations of Base (1% annualchance) Flood Elevations (BFEs) and modified BFEs for communities participating in the National Flood Insurance Program (NFIP), in accordance with section 110 of the Flood Disaster Protection Act of 1973. 42 U.S.C. 4104, and 44 CFR 67.4(a). These proposed BFEs and modified BFEs, together with the floodplain management criteria required by 44 CFR 60.3, are minimum requirements. They should not be construed to mean that the community must change any existing ordinances that are more stringent in their floodplain management requirements. The community may at any time enact stricter requirements of its own or pursuant to policies established by other Federal, State, or regional entities.

These proposed elevations are used to meet the floodplain management requirements of the NFIP and also are used to calculate the appropriate flood insurance premium rates for new buildings built after these elevations are made final, and for the contents in those buildings.

Corrections

In the proposed rule published at 74 FR 46047 in the September 8, 2009, issue of the Federal Register, FEMA published a table under the authority of 44 CFR 67.4. The table entitled "York County, Maine (All Jurisdictions)" addressed the following flooding sources: Atlantic Ocean, Cape Porpoise Harbor, Cleaves Cove, Coffin Brook, Coffin Brook Tributary 1, Driscoll Brook, Ferguson Brook, Goosefare Brook, Keay Brook, Kennebunk River, Little River, Mulloy Brook, Piscataqua River (Town of Kittery), Portsmouth Harbor, Saco River, Sampson Cove, Spruce Creek, The Pool, Worster Brook, and Worster Brook Tributary 3. That table contained inaccurate information as to the location of referenced elevations, effective and modified elevations in feet, or communities affected for the flooding sources "Little River" and "Piscataqua River." In addition, it did not include the following flooding sources: Bonny Eagle Pond, Great East Lake, Jones Brook (backwater effects from Scarborough River), Little Ossipee River, Little River (backwater effects from Scarborough River), Mill Brook (backwater effects from Scarborough River), Mousam River, Piscataqua River (Town of Eliot), Province Lake, Salmon Falls River, and Stump Pond. In this notice, FEMA is publishing a table containing the accurate information, to address these prior errors. The information provided below should be used in lieu of that previously published.

Flooding source(s)	Location of referenced elevation	* Elevation in feet (NGVD) + Elevation in feet (NAVD) # Depth in feet above ground ∧ Elevation in meters (MSL)		Communities affected
		Effective	Modified	
	York County, Maine (All Jurisdic	tions)		
Atlantic Ocean	Along the shoreline, at the intersection of Great Hill Road and Sand Dollar Lane.	+11	+12	City of Biddeford, Town of Kennebunk, Town of Kennebunkport, Town of Kittery, Town of Ogunquit, Town of Old Orchard Beach, Town of Wells, Town of York.

=

Flooding source(s)	Location of referenced elevation	* Elevation in feet (NGVD) + Elevation in feet (NAVD) # Depth in feet above ground ∧ Elevation in meters (MSL)		Communities affected
		Effective	Modified	
	Along the shoreline, approximately 230 feet east of the intersection of Ocean View Lane and Ontio Way.	+14	+33	
Bonny Eagle Pond Cape Porpoise Harbor	Entire shoreline within the Town of Buxton Along the shoreline, at the intersection of Paddy Creek Road and Paddy Creek Hill Road.	None +8	+268 +9	Town of Buxton. Town of Kennebunkport.
Cleaves Cove	Along the shoreline, approximately 330 feet east of the terminus of Harbor Drive.Along the shoreline, approximately 400 feet from the intersection of Turbats Creek Road and Field Point	+13 None	+17 +13	Town of Kennebunkport.
Coffin Brook	Road. Along the shoreline, at the terminus of Halcyon Drive Just upstream of the confluence with Worster Brook Approximately 1.63 mile upstream of the confluence	+13 None None	+22 +133 +254	Town of Berwick.
Coffin Brook Tributary 1	with Worster Brook. Just upstream of the confluence with Coffin Brook Just downstream of Cemetery Road	None None	+141 +320	Town of Berwick.
Driscoll Brook	Approximately 465 feet east of the intersection of State Route 236 and railroad. Just downstream of Blackberry Hill Road	None	+85	Town of Berwick, Town of South Berwick.
Ferguson Brook	Just upstream of the confluence with Worster Brook Just downstream of Cemetery Road	None None	+117 +326	Town of Berwick.
Goosefare Brook	Along the shoreline, at the intersection of Royal Street and Massachusetts Avenue. Along the shoreline, at the intersection of New Salt	+8 None	+9 +15	Town of Old Orchard Beach.
Great East Lake Jones Brook (backwater ef- fects from Scarborough	Road and Grand Avenue. Entire shoreline within the Town of Acton From the Cumberland County boundary to approxi- mately 0.7 mile upstream of the Cumberland Coun- ty boundary.	None +7	+575 +9	Town of Acton. Town of Old Orchard Beach.
River). Keay Brook	Just upstream of the confluence with the Salmon Falls River	None	+186	Town of Berwick.
	Approximately 890 feet south of the terminus of Richardson Drive.	None	+250	
Kennebunk River	Approximately 340 feet south of the terminus of Old Boston Road.	None	+9	Town of Arundel.
Little Ossipee River	Approximately 0.6 mile upstream of Sand Pond Road Approximately 0.9 mile upstream of Sand Pond Road Just upstream of the confluence with the Salmon	None None None	+287 +287 +183	Town of Hollis. Town of Berwick, Town of
	Falls River. Just upstream of the intersection of Little River Road and Dark Hollow Lane.	None	+249	North Berwick.
Little River (backwater effects from Scarborough River).	From the confluence with Mill Brook to approximately 1.4 mile upstream of the confluence with Mill Brook.	+7	+9	Town of Old Orchard Beach.
Mill Brook (backwater effects from Scarborough River).	From the confluence with Jones Brook to approxi- mately 0.8 mile upstream of the confluence with Jones Brook.	+7	+9	Town of Old Orchard Beach.
Mousam River	Approximately 1,900 feet downstream of Main Street (U.S. Route 1).	None	+9	Town of Kennebunk.
Mulloy Brook	Approximately 1,000 feet upstream of Mill Street Just upstream of the confluence with Worster Brook Approximately 1.1 mile upstream of the confluence with Worster Brook.	None None None	+89 +142 +304	Town of Berwick.
Piscataqua River	Along the shoreline, approximately 270 feet south of the intersection of Langston Street and Prince Ave-	+8	+9	Town of Kittery.
	nue. Along the shoreline, approximately 560 feet west of the intersection of Langston Street and Prince Ave- nue.	+8	+14	
Piscataqua River	Just upstream of I–95, at the confluence with Spinney Creek.	+8	+9	Town of Eliot.
Portsmouth Harbor	Approximately 100 feet downstream of Leach Road Along the shoreline, approximately 165 feet east of the intersection of Haley Road and Pepperrell Road.	+8 +8	+9 +9	Town of Kittery.
	Along the shoreline, approximately 390 feet east of the intersection of Bellamy Lane and Pepperrell Road.	+14	+22	
Province Lake		None	+481	Town of Parsonsfield.

Flooding source(s)	Location of referenced elevation	* Elevation in feet (NGVD) + Elevation in feet (NAVD) # Depth in feet above ground ∧ Elevation in meters (MSL)		Communities affected
		Effective	Modified	
Saco River	Along the shoreline, at the terminus of Crestwood Drive.	+8	+9	City of Biddeford.
	Along the shoreline, at the terminus of Reserved Lane.	+13	+16	
Salmon Falls River	Approximately 2.7 miles upstream of New Bridge Road, at the corporate limits.	None	+420	Town of Acton.
Sampson Cove	Just downstream of State Route 109 Along the shoreline, approximately 1,200 feet east of the intersection of Marshall Point Road and Mills Road.	None +8	+511 +14	Town of Kennebunkport.
	Along the shoreline, approximately 720 feet east of the intersection of Fishers Lane and Agamenticus Avenue.	+15	+17	
Spruce Creek	Along the shoreline, approximately 920 feet north of the intersection of Whipple Road and Newson Avenue.	+8	+9	Town of Kittery.
	Along the shoreline, approximately 920 feet north of the intersection of Whipple Road and Newson Avenue.	+8	+13	
Stump Pond The Pool	Entire shoreline within the Town of Newfield Along the shoreline, approximately 560 feet from the intersection of Days Landing and Dory Lane.	None None	+559 +9	Town of Newfield. City of Biddeford.
	Along the shoreline, approximately 490 feet from the intersection of Winter Harbor Lane and Bridge Road.	+8	+11	
Worster Brook	Just upstream of the confluence with the Salmon Falls River.	None	+76	Town of Berwick.
	Approximately 5.8 miles upstream of the confluence with the Salmon Falls River.	None	+228	
Worster Brook Tributary 3	Just upstream of the confluence with Worster Brook Just downstream of Thompson Hill Road	None None	+194 +310	Town of Berwick.

* National Geodetic Vertical Datum.

+ North American Vertical Datum.

Depth in feet above ground.

erenced locations above. Please refer to the revised Flood Insurance Rate Map located at the community map repository (see below) for exact locations of all BFEs to be changed.

Send comments to Roy E. Wright, Deputy Director, Risk Analysis Division, Federal Insurance and Mitigation Administration, Federal Emergency Management Agency, 500 C Street, SW., Washington, DC 20472.

ADDRESSES

City of Biddeford

Maps are available for inspection at City Hall, 205 Main Street, Biddeford, ME 04005.

Town of Acton

Maps are available for inspection at 35 H Road, Acton, ME 04001.

Town of Arundel

Maps are available for inspection at the Town Hall, 468 Limerick Road, Arundel, ME 04046.

Town of Berwick

Maps are available for inspection at the Town Hall, 11 Sullivan Square, Berwick, ME 03901.

Town of Buxton

Maps are available for inspection at the Town Hall, 185 Portland Road, Buxton, ME 04093.

Town of Eliot

Maps are available for inspection at the Town Hall, 1333 State Road, Eliot, ME 03903.

Town of Hollis

Maps are available for inspection at the Town Hall, 34 Town Farm Road, Hollis, ME 04042.

Town of Kennebunk

Maps are available for inspection at the Town Hall, 1 Summer Street, Kennebunk, ME 04043.

Town of Kennebunkport

Maps are available for inspection at the Town Hall, 6 Elm Street, Kennebunkport, ME 04046. Town of Kittery

Maps are available for inspection at the Town Hall, 200 Rogers Road, Kittery, ME 03904.

Town of Newfield

Maps are available for inspection at 637 Water Street, West Newfield, ME 04095.

Town of North Berwick

Flooding source(s)	Location of referenced elevation	+ Elevation ir # Depth in gro ^ Elevatior	feet (NGVD) feet (NAVD) feet above und in meters SL)	Communities affected
		Effective	Modified	
own of Old Orchard Beach Maps are available for inspection own of Parsonsfield Maps are available for inspection own of South Berwick	n at the Town Hall, 23 School Street, Ogunquit, ME n at the Town Hall, 1 Portland Avenue, Old Orchard n at the Town Hall, 62 Federal Road, Parsonsfield, n at the Town Hall, 180 Main Street, South Berwick	d Beach, ME 04064 ME 04047.	I.	

(Catalog of Federal Domestic Assistance No. 97.022, "Flood Insurance.")

Dated: August 10, 2010.

Sandra K. Knight,

Deputy Federal Insurance and Mitigation Administrator, Mitigation, Department of Homeland Security, Federal Emergency Management Agency.

[FR Doc. 2010–20410 Filed 8–17–10; 8:45 am]

BILLING CODE 9110-12-P

DEPARTMENT OF TRANSPORTATION

National Highway Traffic Safety Administration

49 CFR Part 571

[Docket No. NHTSA-2010-0112]

RIN 2127-AK56

Federal Motor Vehicle Safety Standards; Motorcoach Definition; Occupant Crash Protection

AGENCY: National Highway Traffic Safety Administration (NHTSA), Department of Transportation (DOT). **ACTION:** Notice of proposed rulemaking (NPRM).

SUMMARY: In accordance with NHTSA's 2007 Motorcoach Safety Plan and DOT's 2009 Departmental Motorcoach Safety Action Plan, NHTSA is issuing this NPRM to propose to amend the Federal motor vehicle safety standard (FMVSS) on occupant crash protection (FMVSS No. 208) to require lap/shoulder seat belts for each passenger seating position in new motorcoaches. This NPRM also proposes to require a lap/shoulder belt for the motorcoach and large school bus driver's seating positions, which currently are required to have either a

lap or a lap/shoulder belt. Although motorcoach transportation overall is a safe form of transportation in the United States, several motorcoach crashes in 2008 have illustrated that motorcoach rollover crashes, while a relatively rare event, can cause a significant number of fatal or serious injuries in a single event. NHTSA's safety research on motorcoach seat belts, completed in 2009, shows that the installation of lap/shoulder belts on motorcoaches is practicable and effective. We believe that the seat belt assemblies that would be installed on motorcoach passenger seats pursuant to this rulemaking could reduce the risk of fatal injuries in rollover crashes by 77 percent, primarily by preventing occupant ejection in a crash.

DATES: Comments must be received on or before October 18, 2010. Proposed compliance date: 3 years after publication of a final rule.

ADDRESSES: You may submit comments to the docket number identified in the heading of this document by any of the following methods:

• Federal eRulemaking Portal: go to http://www.regulations.gov. Follow the online instructions for submitting comments.

• *Mail:* Docket Management Facility, M–30, U.S. Department of Transportation, West Building, Ground Floor, Rm. W12–140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

• Hand Delivery or Courier: West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue, SE., between 9 am and 5 p.m. Eastern Time, Monday through Friday, except Federal holidays.

• Fax: (202) 493–2251.

Regardless of how you submit your comments, you should mention the docket number of this document. You may call the Docket at 202–366–9324.

Instructions: For detailed instructions on submitting comments and additional information on the rulemaking process, see the Public Participation heading of the Supplementary Information section of this document. Note that all comments received will be posted without change to http:// www.regulations.gov, including any personal information provided.

Privacy Act: Please see the Privacy Act heading under Rulemaking Analyses and Notices.

FOR FURTHER INFORMATION CONTACT: For non-legal issues, Mr. David Sutula, Office of Crashworthiness Standards (*telephone*: 202–366–0247) (*fax*: 202– 366–4921). Mr. Sutula's mailing address is National Highway Traffic Safety Administration, NVS–112, 1200 New Jersey Avenue, SE., Washington, DC 20590.

For legal issues, Ms. Dorothy Nakama, Office of the Chief Counsel (*telephone:* 202–366–2992) (*fax:* 202–366–3820). Ms. Nakama's mailing address is National Highway Traffic Safety Administration, NCC–112, 1200 New Jersey Avenue, SE., Washington, DC 20590.

SUPPLEMENTARY INFORMATION:

Table of Contents

I. Executive Summary

- II. Background
- III. Safety Need
 - a. Rollovers and Ejection
 - b. Motorcoach Crash Backgrounds
- c. NTSB Recommendations
- IV. Motorcoach Safety Initiatives
- a. NHTSA's 2007 Motorcoach Safety Plan
- b. 2009 Departmental Task Force Action Plan
- V. NHTSA Research Results