


§ 42.142 Curve for obtaining Operating Characteristic (OC) curve information for skip lot sampling and inspection.



Notes:

1. This curve applies only to the specific skip lot sampling and inspection plan described in § 42.121 and § 42.123.

2. P_a and P_{as} are essentially equal for values under 50 percent.

[41 FR 42641, Sept. 28, 1976. Redesignated at 42 FR 32514, June 27, 1977 and further redesignated at 45 FR 69424, Oct. 21, 1980 and 46 FR 63203, Dec. 31, 1981]