

## Department of Energy

## § 850.34

(c) Before releasing beryllium-contaminated equipment or other items to another facility performing work with beryllium, the responsible employer must ensure that:

(1) The removable contamination level of equipment or item surfaces does not exceed  $3 \mu\text{g}/100 \text{ cm}^2$ ;

(2) The equipment or item is labeled in accordance with § 850.38(b); and

(3) The equipment or item is enclosed or placed in sealed, impermeable bags or containers to prevent the release of beryllium dust during handling and transportation.

### § 850.32 Waste disposal.

(a) The responsible employer must control the generation of beryllium-containing waste, and beryllium-contaminated equipment and other items that are disposed of as waste, through the application of waste minimization principles.

(b) Beryllium-containing waste, and beryllium-contaminated equipment and other items that are disposed of as waste, must be disposed of in sealed, impermeable bags, containers, or enclosures to prevent the release of beryllium dust during handling and transportation. The bags, containers, and enclosures that are used for disposal of beryllium waste must be labeled according to § 850.38.

### § 850.33 Beryllium emergencies.

(a) The responsible employer must comply with 29 CFR 1910.120(1) for handling beryllium emergencies related to decontamination and decommissioning operations.

(b) The responsible employer must comply with 29 CFR 1910.120(q) for handling beryllium emergencies related to all other operations.

### § 850.34 Medical surveillance.

(a) *General.* (1) The responsible employer must establish and implement a medical surveillance program for beryllium-associated workers who voluntarily participate in the program.

(2) The responsible employer must designate a Site Occupational Medical Director (SOMD) who is responsible for administering the medical surveillance program.

(3) The responsible employer must ensure that the medical evaluations and procedures required by this section are performed by, or under the supervision of, a licensed physician who is familiar with the health effects of beryllium.

(4) The responsible employer must establish, and maintain, a list of beryllium-associated workers who may be eligible for protective measures under this part. The list must be:

(i) Based on the hazard assessment, exposure records, and other information regarding the identity of beryllium-associated workers; and

(ii) Adjusted at regular intervals based on periodic evaluations of beryllium-associated workers performed under paragraph (b)(2) of this section;

(5) The responsible employer must provide the SOMD with the information needed to operate and administer the medical surveillance program, including the:

(i) List of beryllium-associated workers required by paragraph (a)(4) of this section;

(ii) Baseline inventory;

(iii) Hazard assessment and exposure monitoring data;

(iv) Identity and nature of activities or operations on the site that are covered under the CBDPP, related duties of beryllium-associated workers; and

(v) Type of personal protective equipment used.

(6) The responsible employer must provide the following information to the SOMD and the examining physician:

(i) A copy of this rule and its preamble;

(ii) A description of the worker's duties as they pertain to beryllium exposure;

(iii) Records of the worker's beryllium exposure; and

(iv) A description of the personal protective and respiratory protective equipment used by the worker in the past, present, or anticipated future use.

(b) *Medical evaluations and procedures.* The responsible employer must provide, to beryllium-associated workers who voluntarily participate in the medical surveillance program, the medical evaluations and procedures required by this section at no cost and at