

Agreement with the Transmission Provider or the associated OASIS schedule and credit the Reseller with the price reflected in the Assignee's Service Agreement with the Transmission Provider or the associated OASIS schedule; provided that, such credit shall be reversed in the event of non-payment by the Assignee. If the Assignee does not request any change in the Point(s) of Receipt or the Point(s) of Delivery, or a change in any other term or condition set forth in the original Service Agreement, the Assignee will receive the same services as did the Reseller and the priority of service for the Assignee will be the same as that of the Reseller. The Assignee will be subject to all terms and conditions of this Tariff. If the Assignee requests a change in service, the reservation priority of service will be determined by the Transmission Provider pursuant to Section 13.2.

[FR Doc. 2010-23836 Filed 9-23-10; 8:45 am]

BILLING CODE 6717-01-C

DEPARTMENT OF DEFENSE

Department of the Navy

32 CFR Part 706

Certifications and Exemptions Under the International Regulations for Preventing Collisions at Sea, 1972

AGENCY: Department of the Navy, DoD.

ACTION: Final rule.

SUMMARY: The Department of the Navy (DoN) is amending its certifications and exemptions under the International Regulations for Preventing Collisions at Sea, 1972 (72 COLREGS), to reflect that the Deputy Assistant Judge Advocate General (DAJAG) (Admiralty and Maritime Law) has determined that certain vessels of the PC-1 Class are vessels of the Navy which, due to their special construction and purpose, cannot fully comply with certain provisions of the 72 COLREGS without interfering with their special functions as naval ships. The intended effect of

this rule is to warn mariners in waters where 72 COLREGS apply.

DATES: This rule is effective September 24, 2010 and is applicable beginning September 8, 2010.

FOR FURTHER INFORMATION CONTACT:

Lieutenant Commander Ted Cook, JAGC, U.S. Navy, Admiralty Attorney, (Admiralty and Maritime Law), Office of the Judge Advocate General, Department of the Navy, 1322 Patterson Ave., SE., Suite 3000, Washington Navy Yard, DC 20374-5066, telephone number: 202-685-5040.

SUPPLEMENTARY INFORMATION: Pursuant to the authority granted in 33 U.S.C. 1605, the DoN amends 32 CFR part 706.

This amendment provides notice that the DAJAG (Admiralty and Maritime Law), under authority delegated by the Secretary of the Navy, has certified that certain vessels of the PC-1 Class are vessels of the Navy which, due to their special construction and purpose, cannot fully comply with the following specific provisions of 72 COLREGS without interfering with their special function as naval ships: Rule 21(a) pertaining to the arc of visibility of a masthead light. The DAJAG (Admiralty and Maritime Law) has also certified that the lights involved are located in

closest possible compliance with the applicable 72 COLREGS requirements.

Moreover, it has been determined, in accordance with 32 CFR parts 296 and 701, that publication of this amendment for public comment prior to adoption is impracticable, unnecessary, and contrary to public interest since it is based on technical findings that the placement of lights on this vessel in a manner differently from that prescribed herein will adversely affect the vessel's ability to perform its military functions.

List of Subjects in 32 CFR Part 706

Marine safety, Navigation (water), and Vessels.

■ For the reasons set forth in the preamble, the DoN amends part 706 of title 32 of the CFR as follows:

PART 706—CERTIFICATIONS AND EXEMPTIONS UNDER THE INTERNATIONAL REGULATIONS FOR PREVENTING COLLISIONS AT SEA, 1972

■ 1. The authority citation for part 706 continues to read as follows:

Authority: 33 U.S.C. 1605.

■ 2. Section 706.2 is amended in Table Three by removing the entry for USS

Zephyr and revising the following entries for the PC-1 Class to read as follows:

§ 706.2 Certifications of the Secretary of the Navy under Executive Order 11964 and 33 U.S.C. 1605.

* * * * *

TABLE THREE

Vessel	No.	Masthead lights arc of visibility; rule 21(a)	Side lights arc of visibility; rule 21(b)	Stern light arc of visibility; rule 21(c)	Side lights distance inboard of ship's sides in meters 3(b) annex 1	Stern light, distance forward of stern in meters; rule 21(c)	Forward anchor light, height above hull in meters; 2(K) annex 1	Anchor lights relationship of aft light to forward light in meters 2(K) annex 1
USS TEMPEST	PC 2	(2)				1 28.3	3.0	1.1 below.
USS HURRICANE	PC 3	(2)				1 28.5	3.0	1.1 below.
USS MONSOON	PC 4	(2)				1 28.3	3.0	1.1 below.
USS TYPHOON	PC 5	(2)				1 28.5	3.0	1.1 below.
USS SIROCCO	PC 6	(2)				1 28.5	3.0	1.1 below.
USS SQUALL	PC 7	(2)				1 28.5	3.0	1.1 below.
USS CHINOOK	PC 9	(2)				1 28.5	3.0	1.1 below.
USS FIREBOLT	PC 10	(2)				1 28.5	3.0	1.1 below.
USS WHIRLWIND	PC 11	(2)				1 28.5	3.0	1.1 below.
USS THUNDERBOLT	PC 12	(2)				1 28.5	3.0	1.1 below.

¹ Only when towing

² Lower forward masthead light (used for towing) is partially blocked at angles plus or minus 8.5 degrees off centerline; this light is used only when tow exceeds 200 meters from the stern of the ship to aft end of tow.

Approved: September 8, 2010.

M. Robb Hyde,

Commander, JAGC, U.S. Navy, Deputy Assistant Judge Advocate, General (Admiralty and Maritime Law).

[FR Doc. 2010-23749 Filed 9-23-10; 8:45 am]

BILLING CODE 3810-FF-P

DEPARTMENT OF HOMELAND SECURITY

Coast Guard

33 CFR Part 3

[Docket No. USCG-2010-0351]

RIN 1625-ZA25

Navigation and Navigable Waters; Technical, Organizational, and Conforming Amendments, Sector Puget Sound, WA; Correction

AGENCY: Coast Guard, DHS.

ACTION: Final rule; correction.

SUMMARY: The Coast Guard published in the *Federal Register* of August 5, 2010, a document concerning non-substantive changes to Title 33 Parts 3 and 165 of the Code of Federal Regulations. That publication contained an error in amendatory instruction 2 and its regulatory text for part 3. This document corrects this error.

DATES: This correction is effective September 24, 2010.

FOR FURTHER INFORMATION CONTACT: If you have questions on this rule, call or e-mail Lt. Matthew Jones, Coast Guard; telephone 206-220-7110, e-mail *Matthew.m.jones@uscg.mil*. If you have questions on viewing the docket, call Renee V. Wright, Program Manager, Docket Operations, telephone 202-366-9826.

SUPPLEMENTARY INFORMATION: In FR doc 2010-19326 appearing on page 47212 in the issue of Thursday, August 5, 2010, the following correction is made:

1. On page 47212, in the second column, revise amendatory instruction number 2 to read as follows:
"Revise § 3.65-10 to read as follows:

§ 3.65-10 Sector Puget Sound Marine Inspection Zone and Captain of the Port Zone.

Sector Puget Sound's office is located in Seattle, WA. The boundaries of Sector Puget Sound's Marine Inspection and Captain of the Port Zones start at latitude 48°29'35" N, longitude 124°43'45" W, proceeding along the Canadian border east to the Montana-North Dakota boundary; thence south along this boundary to the Wyoming state line; thence west and south along the Montana-Wyoming boundary to the Idaho state line; thence northwest along the Montana-Idaho boundary to latitude 46°55'00" N; thence west along latitude

46°55'00" N to longitude 123°18'00" W; thence north to a point latitude 47°32'00" N, longitude 123°18'00" W; thence west along latitude 47°32'00" N to the outermost extent of the EEZ; thence northeast along the outermost extent of the EEZ to the Canadian border; thence east along the Canadian border to the point of origin."

Dated: September 21, 2010.

Sandra Selman,

CDR, USCG, Acting Chief, Office of Regulations and Administrative Law, United States Coast Guard.

[FR Doc. 2010-24015 Filed 9-23-10; 8:45 am]

BILLING CODE P

DEPARTMENT OF HOMELAND SECURITY

Coast Guard

33 CFR Part 165

[Docket No. USCG-2010-0823]

RIN 1625-AA00

Safety Zone; Chicago Harbor, Navy Pier Southeast, Chicago, IL

AGENCY: Coast Guard, DHS.

ACTION: Notice of enforcement of regulation.

SUMMARY: The Coast Guard will enforce the Navy Pier Southeast Safety Zone in