

to the Regional Supervisor which demonstrates, in the judgment of the Regional Supervisor, that projected emissions from an otherwise exempt facility will, either individually or in combination with other facilities in the area, significantly affect the air quality of an onshore area, then the Regional Supervisor shall require the lessee to submit additional information to determine whether control measures are necessary. The lessee shall be given the opportunity to present information to the Regional Supervisor which demonstrates that the exempt facility is not significantly affecting the air quality of an onshore area of the State.

(g) *Emission monitoring requirements.* The lessee shall monitor, in a manner approved or prescribed by the Regional Supervisor, emissions from the facility following the installation of emission controls. The lessee shall submit this information monthly in a manner and form approved or prescribed by the Regional Supervisor.

(h) *Collection of meteorological data.* The Regional Supervisor may require the lessee to collect, for a period of time and in a manner approved or prescribed by the Regional Supervisor, and submit meteorological data from a facility.

[53 FR 10690, Apr. 1, 1988; 53 FR 26067, July 11, 1988. Redesignated and amended at 63 FR 29479, 29485, May 29, 1998; 64 FR 72794, Dec. 28, 1999]

Subpart D—Oil and Gas Drilling Operations

GENERAL REQUIREMENTS

§ 250.400 Who is subject to the requirements of this subpart?

The requirements of this subpart apply to lessees, operating rights owners, operators, and their contractors and subcontractors.

[68 FR 8423, Feb. 20, 2003]

§ 250.401 What must I do to keep wells under control?

You must take necessary precautions to keep wells under control at all times. You must:

(a) Use the best available and safest drilling technology to monitor and evaluate well conditions and to mini-

mize the potential for the well to flow or kick;

(b) Have a person onsite during drilling operations who represents your interests and can fulfill your responsibilities;

(c) Ensure that the toolpusher, operator's representative, or a member of the drilling crew maintains continuous surveillance on the rig floor from the beginning of drilling operations until the well is completed or abandoned, unless you have secured the well with blowout preventers (BOPs), bridge plugs, cement plugs, or packers;

(d) Use personnel trained according to the provisions of subpart O; and

(e) Use and maintain equipment and materials necessary to ensure the safety and protection of personnel, equipment, natural resources, and the environment.

[68 FR 8423, Feb. 20, 2003]

§ 250.402 When and how must I secure a well?

Whenever you interrupt drilling operations, you must install a downhole safety device, such as a cement plug, bridge plug, or packer. You must install the device at an appropriate depth within a properly cemented casing string or liner.

(a) Among the events that may cause you to interrupt drilling operations are:

- (1) Evacuation of the drilling crew;
- (2) Inability to keep the drilling rig on location; or
- (3) Repair to major drilling or well-control equipment.

(b) For floating drilling operations, the District Supervisor may approve the use of blind or blind-shear rams or pipe rams and an inside BOP if you don't have time to install a downhole safety device or if special circumstances occur.

[68 FR 8423, Feb. 20, 2003]

§ 250.403 What drilling unit movements must I report?

(a) You must report the movement of all drilling units on and off drilling locations to the District Supervisor. This includes both MODU and platform rigs. You must inform the District Supervisor 24 hours before: